

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106  
 BASDEN RV CENTER INC  
 DBA AMERICAN RV CENTER  
 600 E BASELINE ROAD  
 EVANSVILLE, IN 47725  
 USA

CLAIM STATUS Authorized  
 CLAIM 1290846  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2FEPB0MW020259  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 320 / 320  
 ITEM # FET248RBS-320  
 DEALER RO # 69042  
 CLAIM START DATE 10/24/2022  
 CLAIM END DATE 01/01/1900

Labor rate: \$150.00

**OWNER INFORMATION**

GLORIA J NALLY  
 2406 GLENVIEW DR  
 Evansville, IN 47720  
 USA

Retail Date of Purchase 07/28/2021

WARRANTY EXPIRATION DATE 07/28/2022

**Claim Line Details**

**Labor**

Line# 1	Operation Code RC-026-01-00-004186	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code
<b>Complaint, Cause, Correction</b>		
Original Note : bhoffman@americanrvcenter.com, 2022-10-24 16:15:39 :: RECALL 22V243 LP QUICK CONNECT REPLACED LP QUICK CONNECT		
Model #	Dlr Sub Hrs	0.30
Serial #	Appr Hrs	0.60
	Sub Labor Amt	\$45.00
	Appr Labor Amt	\$90.00

**Notes**

. Did you inspect/replace BOTH quick disconnects? All Freedom Ultra Lites and Freedom Liberty/Maple Leaf Models will require 2 quick disconnects. One for the frame mounted quick disconnect location on the unit and one for the gas supply line attached to the griddle. The Recall is not complete until BOTH are inspected/replaced. Even though the disconnect is not cracked at this time, if the disconnect has "ENERCO GROUP" etched on the slider they need replaced.  
 FOUND IT AND CHANGED IT  
 R&R 2 quick disconnects as per recall 22V243; VCB;

**Submitted**

Labor Amt	\$45.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$45.00</b>

**Approved**

Labor Amt	\$90.00
Parts & Freight	\$0.00
<b>Total</b>	<b>\$90.00</b>

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE

All repairs described have been inspected and are satisfactory.