

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 US  
 47725  
 812-867-5200

WARRANTY CLAIM # 69737  
 MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO  
 Customer: 1000 - BASDEN'S AMERICAN RV  
 Address: 600 E. BASELINE RD. EVANSVILLE, IN  
 USA  
 47725

Phone:

Stock Number: 11227 - 2022 SPRINGDALE 260BH 4YDTSGL29N3111744

VIN: 4YDTSGL29N3111744 HIN:

SER#: 4YDTSGL29N3111744

Mileage: 0

Work Order Comp: 08 FEB 23

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 26 JAN 23

Inv #: 387414

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
69737	3	BRING UNIT IN AND FIND WHERE ALL THE PAPER IS COMING LOOSE AND MARK IT WITH BLUE TAPE	
		BRING UNIT IN AND FIND WHERE ALL THE PAPER IS COMING LOOSE AND MARK IT WITH BLUE TAPE ON WOOD CABINET FRAMES.	
		Checked all wood in unit. Found peeling of cabinet frames on the majority of cabinet fronts.Placed blue tape to mark all locations. Measured all damaged cabinet frames. 1/27/2023: Turned in parts request for material to cover all damaged frame pieces.	
69737	1	ENTRY DOOR WONT SHUT	
		ENTRY DOOR WON'T SHUT.	
		Checked operation of entry door. Striker plate will noy adjust out far enough for door to latch on it. Removed striker plate. Filed door frame material to allow latch late to move fsrther out so thgat door latch can grab it. Door has a slight bow outin it at latch. Straightened door and remounted latch plate on door jamb frame. Checked operation again. Door now latches closed.	

\*\*\*\*\*

69737 3 BRING UNIT IN AND FIND WHERE ALL THE PAPER IS COMING LOOSE AND MARK IT WITH BLUE TAPE

BRING UNIT IN AND FIND WHERE ALL THE PAPER IS COMING LOOSE AND MARK IT WITH BLUE TAPE ON WOOD CABINET FRAMES.

Checked all wood in unit. Found peeling of cabinet frames on the majority of cabinet fronts.Placed blue tape to mark all locations. Measured all damaged cabinet frames. 1/27/2023: Turned in parts request for material to cover all damaged frame pieces.

69737 1 ENTRY DOOR WONT SHUT

ENTRY DOOR WON'T SHUT.

Checked operation of entry door. Striker plate will noy adjust out far enough for door to latch on it. Removed striker plate. Filed door frame material to allow latch late to move fsrther out so thgat door latch can grab it. Door has a slight bow outin it at latch. Straightened door and remounted latch plate on door jamb frame. Checked operation again. Door now latches closed.

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
685519	3	6" - UNI MAT GREY		44.00	0.89	39.16

\*\*\*\*\*

685519 3 6" - UNI MAT GREY 44.00 0.89 39.16

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	3	MISCELLANEOUS REPAIR		0.00	150.00	0.00

\*\*\*\*\*

Z990 3 MISCELLANEOUS REPAIR 0.00 150.00 0.00

Claim : 69737

```
*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      3  MISCELLANEOUS REPAIR          0.50    150.00    75.00
Z990      3  MISCELLANEOUS REPAIR          0.80    150.00   120.00
Z990      3  MISCELLANEOUS REPAIR          0.10    150.00    15.00
Z990      3  MISCELLANEOUS REPAIR          0.90    150.00   135.00
Z990      3  MISCELLANEOUS REPAIR          1.00    150.00   150.00
Z990      3  MISCELLANEOUS REPAIR          1.50    150.00   225.00
Z990      3  MISCELLANEOUS REPAIR          3.50    150.00   525.00
Z990      3  MISCELLANEOUS REPAIR          0.50    150.00    75.00
Z990      3  MISCELLANEOUS REPAIR          4.00    150.00   600.00
Z990      3  MISCELLANEOUS REPAIR          2.50    150.00   375.00
Z990      1  MISCELLANEOUS REPAIR          0.20    150.00    30.00
*****
```

```
*****
Excode    Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT       3  FREIGHT                          1.00    15.99    15.99
*****
```

Parts Total: 39.16  
Labour Total: 2,325.00  
Sublet Total: 0.00  
Extras Total: 15.99

>>>> Claim Total: 2,380.15

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_