



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69766
Promised Date: 27 JAN 23

CUSTOMER WORK ORDER

WO #: 69766

Customer: 51673 - GENTRY, MARY L. -
618-839-9248

Tag:

Author: BH

Location: 0202 GET PREAUTH DONE

Stock #: 11223

Stock Desc: 2022 TT KEYSTONE
SPRINGDALE 202RD

Chassis #: 4YDTSGJ2XN311674

Serial #: 4YDTSGJ2XN311674

Mileage:

Licence:

Invoice #:

Date In: 31 JAN 23

Promised: 27 JAN 23

Date Sched:

Completed: 31 JAN 23

Warr. Date: 27 JAN 23

Job #1 - Warranty

COMPLAINT: SUPPORT BEAM FOR THE DINETTE IS BROKEN

CAUSE: SUPPORT IS BROKEN UNDER DINETTE SEAT.

CORRECTION: REMOVED DAMAGED BEAM WITH MUTI TOOL. CUT NEW BEAM TO LENGTH.
DRILLED OUT PILOY HOLES ON ENDS TO TOENAIL INTO SURROUNDING FRAME. SECURED WITH
SCREWS. CLEANED UP MESS.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	30.00

Subtotal for Job #1: 30.00

Job #2 - Internal

COMPLAINT: CLOSET DOOR IN BEDROOM WONT LATCH

CAUSE: LATCH IS UNDER NEATH DOOR HOLDER.

CORRECTION: REPOSITIONED LATCH

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

REAR CORNERS ON THE ROOF NEEDS DICOR

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: REAR INSERT TRIM IS TOO SHORT NEEDS REPLACED

CAUSE: INSERT TRIM NEEDS REPLACED.

CORRECTION: REMOVED SCREW THAT HOLDS INSERT TRIM UNDER CORNER CAP. REMOVED
INSERT TRIM. TOOK NEW TRIM AND A HEAT GUN TO MAKE INSERT TRIM FLEXABLE. INSTALLED
TRIM WITH PUTTY BUDDY. INSTALLED SCREWS.



Customer #:
51673

W/O: 69166
Promise Date:
27 JAN 23



Customer #:
51673



Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	30.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

Parts Part #	Description	Qty	Price	Total
20-1421	1" x 25' VINYL INSERT BLA	1.00	6.19	6.19

Subtotal for Job #4: 36.19

Job #5 - Internal

COMPLAINT: REAR BLIND WONT STAY UP

CAUSE: BLIND WONT STAY UP.

CORRECTION: ADJUSTED STRING TENSION. BLIND HOLDS ITSELF UP NOW.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: REAR MARKER LIGHT DOESNT WORK RED

CAUSE: MARKER LIGHT IS INOP. REMOVED COVER AND LIGHT DIODE HAS CORROSION ON IT.

CORRECTION: REMOVED MARKER LIGHT AND RELACED WITH NEW ONE. SEALED WITH SILICONE.

Labor Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	30.00

Parts Part #	Description	Qty	Price	Total
210631	MCL32RBS 3-LED RED MARKER LIGHT	1.00	4.80	4.80

Subtotal for Job #6: 34.80

Parts Total: 10.99
Labour Total: 90.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 100.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 01 Feb 2023

