



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 69907
Promised Date:
28 FEB 23

CUSTOMER WORK ORDER

WO #: 69907

Customer: 1000 - BASDEN'S
AMERICAN RV -

Tag:

Author: BH

Location: 0323 CHECK STATUS WITH
RAB

Stock #: 10845

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE GREY WOLF 23MKBL

Chassis #: 4X4TCKY29PK085838

Serial #: 4X4TCKY29PK085838

Mileage: 0

Licence:

Invoice #:

Date In: 23 FEB 23

Promised: 28 FEB 23

Date Sched:

Completed: 21 MAR 23

Warr. Date:

Job #1 - Warranty

COMPLAINT: SEAL UNDER SLIDE COMING OFF

CAUSE: SEAL UNDER SLIDE IS COMING OFF THE SCREWS HOLDING IT FELL OUT. REMOVED OLD SEALANT WHICH WAS STUCK ON THERE PRETTY GOOD AND SLID SEAL BACK ON AND INSTALLED TWO NEW BLACK SELFTAPPING SCREWS TO HOLD IT IN PLACE. ONCE SECURED I RESEALED AROUND THE SEAL

CORRECTION: SEAL UNDER SLIDE IS COMING OFF THE SCREWS HOLDING IT FELL OUT. REMOVED OLD SEALANT WHICH WAS STUCK ON THERE PRETTY GOOD AND SLID SEAL BACK ON AND INSTALLED TWO NEW BLACK SELFTAPPING SCREWS TO HOLD IT IN PLACE. ONCE SECURED I RESEALED AROUND THE SEAL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	104.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	-104.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: ZEBRA SLIDE BLIND NOT WORKING

CAUSE: ZEBRA SLIDE BLINDS NOT WORKING RIGHT. ON FURTHER INSPECTION I FOUND FABRIC WAS TORN AND MAIN METAL BEAM WAS BENT CAUSING IT NOT TO GO UP AND DOWN PROPERLY. NEEDS NEW ONE INSTALLED

CORRECTION: ZEBRA SLIDE BLINDS NOT WORKING RIGHT. ON FURTHER INSPECTION I FOUND FABRIC WAS TORN AND MAIN METAL BEAM WAS BENT CAUSING IT NOT TO GO UP AND DOWN PROPERLY. NEEDS NEW ONE INSTALLED

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

Parts

Part #	Description	Qty	Price	Total
F100141513	SHADE, 64" X 24" ZEBRA SHADE / 2020	1.00	80.78	80.78



Customer #:
1000

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SHADE	1.00	31.51	31.51
Subtotal for Job #2:				144.29

Job #3 - Warranty

COMPLAINT: ENRTY DOOR RUBS

CAUSE: ENTRY DOOR WAS HIITING STRIKING PLATE CASUING IT TO RUB. ADJUSTED STRIKING PLATE AND TESTTED DOOR WHICH FIXED THE PROBLEM

CORRECTION: ENTRY DOOR WAS HIITING STRIKING PLATE CASUING IT TO RUB. ADJUSTED STRIKING PLATE AND TESTTED DOOR WHICH FIXED THE PROBLEM

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00
Subtotal for Job #3:			48.00

Parts Total:	80.78
Labour Total:	80.00
Sublet Total:	0.00
Extras Total:	31.51
WORK ORDER TOTAL:	192.29

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Mar 2023

W/O: 69907
Promised Date:
28 FEB 23Customer #:
1000