

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69913
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 10996 - 2023 CATALINA SUMMIT SERIES 271DBS 5ZT2CASB2PU041638
VIN: 5ZT2CASB2PU041638 HIN: SER#: 5ZT2CASB2PU041638
Mileage: 0 Work Order Comp: 07 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 23 FEB 23 Inv #: 388245

WO # Job # Description JOB INFORMATION

69913 1 FRONT SLIDE SKI NOT INSTALLED RIGHT CAN SEE WOOD
BROUGHT CAMPER INTO SERVICE BAY THEN PLUG UNIT IN. MOVED
SLIDEROOM OUT TO INSPECT THE SKI. REMOVED SCREWS THEN THE SKI
FROM SLIDEOUT. TOOK PICTURES OF PROGRESS. INSTALLED SKI AND TRIM
WITH SCREWS FOR WATER TIGHT SEAL. TRIMED WITH SILICONE.

69913 2 REAR DOOR OPENS BUT REALLY HARD TO CLOSE
CHECKED THE DOOR OPEN AND CLOSE FUNCTION. ONLY THE THAT COULD BE
FOUND WAS A RED CLIP AT THE TOP OF THE DOOR. REMOVED THAT RED
CLIP DOOR SEEMS TO CLOSE BETTER WITH NO PROBLEM.

69913 3 DOOR SIDE REAR CABINET WALL BOARD IS LOOSE
OPENED THE DOOR TO THE REAR CABINET AND THE TOP SHELF AREA THE
SEAM TAPE WAS NOT STUCK ON PROPER. LOOKED FOR TAPE THAT MATCH THE
SAME COLOR AS THE WALL. THEN CUT 2 18 INCH STRIPS TO COVER OVER
THE SECTION THAT WAS COMING OFF. PEELED AND STUCK THOSE STRIPS TO
THE WALL. STRIPS MATCH PERFECTLY.

69913 4 PANTRY DOOR RUBS ON THE BOTTOM
OPENED AND CLOSED PANTRY DOOR TOSEE HOW MUCH NEEDS TO BE TRIMED.
OPENED DOOR THEN REMOVED THE SCREW AT THE LATCHING PLATE. THEN
PULLED THE DOOR FRAME MOLDING OFF. KNOCK BAD THE STUD AND PUT A
STEEL PLATE UNDER THE DOOR FRAME TO PROTECT THE FLOOR. TRIM THE
BOTTOM STUD AN 1/8 INCH THEN CHECKED THE CLEARANCE OF DOOR BY
SETTING IN THE FRAME MOLDING. HAVE CLEARANCE NOW. SILICONED THE
BACKSIDE OF MOLDING THEN PUT THE LATCH PLATE BACK ON.

Claim : 69913

 WO # Job # Description JOB INFORMATION

69913 5 LR TO BR DOOR RUBS WONT STAY SHUT
 CHECKED THE DOOR BY OPENING AND CLOSING THE DOOR TO FIND THE
 ISSUE. THE DOOR LATCH PLATE NEEDED TO BE MOVED OUTWARD. THE DOOR
 ITSELF NEEDED TO BE PUSHED OVER TO THE LATCH PLATE. PUT SOME
 BATTON IN THE DOOR FRAME TO PUSH THE DOOR OVER. REMOVED THE LATCH
 PLATE DRILLED OUT THE HOLE BIGGER TO HAVE MORE ROOM FOR THE LATCH
 PLATE. PUT LATCH PLATE BACK ON NOW DOOR SHUTS WITH EASE. TOOK
 PICTURES OF PROGRESS.

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	160.00	80.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	160.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.40	160.00	64.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.40	160.00	64.00

Parts Total: 0.00
 Labour Total: 272.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 272.00

Customer Signature: _____

Date: _____