

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 69919
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11094 - 2022 CATALINA 293QBCKLE 5ZT2CAUB0NX026077
VIN: 5ZT2CAUB0NX026077 HIN: SER#: 5ZT2CAUB0NX026077
Mileage: 0 Work Order Comp: 23 MAR 23
Auth. No: Dealer #:
Warr. Date: Work Order Date: 23 FEB 23 Inv #: 388776

WO # Job # Description JOB INFORMATION

69919 7 UNDER SINK 2 AREAS IN THE CABINET THERE IS WOOD LOOSE
under sink wood panel is lose do to it being chipped and broke
needs new one
under sink wood panel is lose do to it being chipped and broke
needs new one

69919 1 OUTSIDE FRIDGE DOOR SEAL DOESNT SHUT ALL THE WAY
OUTSIDE FRIDGE DOOR WONT SHUT ALL THE WAY AS THE SEAL HAD COME
LOSE, REATTACHED SEAL AND IT SHUT RIGHT
OUTSIDE FRIDGE DOOR WONT SHUT ALL THE WAY AS THE SEAL HAD COME
LOSE, REATTACHED SEAL AND IT SHUT RIGHT

69919 2 ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME
ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME, DUE TO LATCH ON
SCREEN DOOR BEING INSTALLED CRROKED. TEMOVED SCREEN DOOR LATCH
AND REINSTALLED TO THE PROPER POSTION
ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME, DUE TO LATCH ON
SCREEN DOOR BEING INSTALLED CRROKED. TEMOVED SCREEN DOOR LATCH
AND REINSTALLED TO THE PROPER POSTION

69919 3 SLIDING BUNK DOOR
sliding bunk door was off the track removed track to readjust
door and reattached track/stop and tested
sliding bunk door was off the track removed track to readjust
door and reattached track/stop and tested

Claim : 69919

 WO # Job # Description JOB INFORMATION

69919 4 BEDROOM DOOR RUBS
 BEDROOM DORR WAS RUBBING DO TO HINGES OF DOOR NOT ALL THE WATY
 IN. SCREWED IN HINGES AND IT SOLVED THE PROBLEM
 BEDROOM DORR WAS RUBBING DO TO HINGES OF DOOR NOT ALL THE WATY
 IN. SCREWED IN HINGES AND IT SOLVED THE PROBLEM

69919 5 BUNKROOM ODS CABINET RUB
 BUNKROOM CABNIET DOORS WERE RUBBING AS THEY WERE INSTALLED TO
 CLOSE TOGETHER. REMOVED ONE DOOR AND ADJUSTED POSTION. REMOVED
 LATCH AS WELL WHICH FIXED THE PROBLEM
 BUNKROOM CABNIET DOORS WERE RUBBING AS THEY WERE INSTALLED TO
 CLOSE TOGETHER. REMOVED ONE DOOR AND ADJUSTED POSTION. REMOVED
 LATCH AS WELL WHICH FIXED THE PROBLEM

69919 6 ENTRY DOOR SEAL COMING OFF
 ENTRY DOOR SEAL WAS COMING OFF NEEDED SOM ADHESIVE. ADDED SOME
 ADHESIVE AND STUCK BACK ON
 ENTRY DOOR SEAL WAS COMING OFF NEEDED SOM ADHESIVE. ADDED SOME
 ADHESIVE AND STUCK BACK ON

 Part No Job# Description PARTS Qty Price Total

 F100301817 7 PANELING, HDF 2.7 MM X 4' X 8' CH 32.00 1.40 44.80

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.40 160.00 64.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.30 160.00 48.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 7 FREIGHT 1.00 344.11 344.11

Parts Total: 44.80
 Labour Total: 256.00
 Sublet Total: 0.00
 Extras Total: 344.11

>>>> Claim Total: 644.91

Customer Signature: _____

Date: _____

