

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1452474
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAUB0NX026077
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT293QBCKLE
		DEALER RO #	69919
		CLAIM START DATE	03/09/2023
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description	
70-675-01-11-003364	Hotpoint Mini Refrigerator - Appliances/Mini Refrigerator (Hotpoint)/Replace/Electrical	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 10:55:49 :: OUTSIDE FRIDGE DOOR SEAL DOESNT SHUT ALL THE WAY OUTSIDE FRIDGE DOOR WONT SHUT ALL THE WAY AS THE SEAL HAD COME LOSE, REATTACHED SEAL AND IT SHUT RIGHT OUTSIDE FRIDGE DOOR WONT SHUT ALL THE WAY AS THE SEAL HAD COME LOSE, REATTACHED SEAL AND IT SHUT RIGHT		
Model #	Dlr Sub Hrs	Sub Labor Amt
HME02AAMBBB	0.30	\$48.00
Serial #	Appr Hrs	Appr Labor Amt
TS016562	0.20	\$32.00
Notes		
EXCESSIVE AMOUNT REQUESTED. ADJUSTED TO TYPICAL REPAIR TIME TO REATTACH THE SEAL. REPAIR NOT REPLACE		

Labor

Line# 2

Operation Code	Operational Description	
02-20-66-000664	Entry Door - RV - Adjust/Exterior/Entry Doors	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 11:03:45 :: ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME, DUE TO LATCH ON SCREEN DOOR BEING INSTALLED CRROKED. TEMOVED SCREEN DOOR LATCH AND REINSTALLED TO THE PROPER POSTION ENTRY DOOR AND SCREEN WONT OPEN AT THE SAME TIME, DUE TO LATCH ON SCREEN DOOR BEING INSTALLED CRROKED. TEMOVED SCREEN DOOR LATCH AND REINSTALLED TO THE PROPER POSTION		
Model #	Dlr Sub Hrs	Sub Labor Amt
	0.10	\$16.00
Serial #	Appr Hrs	Appr Labor Amt
	0.10	\$16.00
Notes		
AUTHORIZED AS REQUESTED		

Labor

Line# 3

Operation Code	Operational Description	
30-101-24-00-001079	Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 11:04:49 :: SLIDING BUNK DOOR sliding bunk door was off the track removed track to readjust door and reattached track/stop and tested sliding bunk door was off the track removed track to readjust door and reattached track/stop and tested		
Model #	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$48.00
Serial #	Appr Hrs	Appr Labor Amt
	0.30	\$48.00

Notes

Labor
Line# 4

Operation Code
02-30-101-001076

Operational Description
Hinged Passage Door - Adjust/Interior/Interior Doors

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 11:05:49 :: BEDROOM DOOR RUBS BEDROOM DORR WAS RUBBING DO TO HINGES OF DOOR NOT ALL THE WATY IN. SCREWED IN HINGES AND IT SOLVED THE PROBLEM BEDROOM DORR WAS RUBBING DO TO HINGES OF DOOR NOT ALL THE WATY IN. SCREWED IN HINGES AND IT SOLVED THE PROBLEM

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes
AUTHORIZED AS REQUESTED

Labor
Line# 5

Operation Code
24-30-100-001035

Operational Description
Cabinet Door - Repair/Interior/Cabinetry

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 11:08:20 :: BUNKROOM ODS CABINET RUB BUNKROOM CABNIET DOORS WERE RUBBING AS THEY WERE INSTALLED TO CLOSE TOGETHER. REMOVED ONE DOOR AND ADJUSTED POSTION. REMOVED LATCH AS WELL WHICH FIXED THE PROBLEM BUNKROOM CABNIET DOORS WERE RUBBING AS THEY WERE INSTALLED TO CLOSE TOGETHER. REMOVED ONE DOOR AND ADJUSTED POSTION. REMOVED LATCH AS WELL WHICH FIXED THE PROBLEM

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes
AUTHORIZED AS REQUESTED

Labor
Line# 6

Operation Code
20-66-19-00-000664

Operational Description
Entry Door - RV - Exterior/Entry Doors/Reseal/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 11:09:20 :: ENTRY DOOR SEAL COMING OFF ENTRY DOOR SEAL WAS COMING OFF NEEDED SOM ADHESIVE. ADDED SOME ADHESIVE AND STUCK BACK ON ENTRY DOOR SEAL WAS COMING OFF NEEDED SOM ADHESIVE. ADDED SOME ADHESIVE AND STUCK BACK ON

Model #	Dlr Sub Hrs	0.20	Sub Labor Amt	\$32.00
Serial #	Appr Hrs	0.20	Appr Labor Amt	\$32.00

Notes

Labor
Line# 7

Operation Code
01-30-102-002279

Operational Description
Wall Panel - Replace/Interior/Panels, Ceilings, & Interior Moldings

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2023-03-09 11:10:10 :: UNDER SINK 2 AREAS IN THE CABINET THERE IS WOOD LOOSE under sink wood panel is lose do to it being chipped and broke needs new one under sink wood panel is lose do to it being chipped and broke needs new one

Model #	Dlr Sub Hrs	0.40	Sub Labor Amt	\$64.00
Serial #	Appr Hrs	0.40	Appr Labor Amt	\$64.00

Notes
AUTHORIZED AS REQUESTED

Submitted

Labor Amt	\$272.00
Parts & Freight	\$0.00
Total	\$272.00

Approved

Labor Amt	\$256.00
Parts & Freight	\$0.00
Total	\$256.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.