

e-Authorization

4/26/20
10:21:11

3-Authorization number PA03413045 Reference no: 70308 Status: Approved Approved by samya Approved date 4/18/2023
rving Name Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTCGP21NV507131 3/16/2023
600 E Baseline Rd
Evansville, IN 47725

du Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
------------------------------	-------------	--------	-----------	-------------------	-----------------	-----	---------------	--------------------------------

1	5102816A Light, LED-Striplig	0.00	1.50	1.00		1	0.30	Complaint:FRONT CAP WINDOW LEAKING. ALSO THE TRIM ON THE INSIDE OF THIS WINDOW DOES NOT SEEM TO BE INSTALLED CORRECTLY Cause:UNIT LEAKING WILL HAVE TO REPLACE THE TRIM ABOVE THE BED Correction:set up for water test out side,remove trim for window over bed, has water damage, wood is ceacked, water test for leak, found water getting in around LED light wires above window, reseal wires, let sealer set up over night retest with water,, turn in po for trim, close up unit and bring in bay
---	---------------------------------	------	------	------	--	---	------	--

						Qty	Hours	Sub operation	Description
						2	0.20	3201808B	Decorative Wood Trim - Replace - r

2	6105215B Toilet - All - Floor	0.00	1.00	1.00		1	1.00		Complaint:LEAK AROUND THE BASE OF THE TOILET Cause:test for leaks traced to floor gasket, install new floor gasket Correction:test for leaks traced to floor gasket, install new floor gasket
---	----------------------------------	------	------	------	--	---	------	--	---

KRV – Labor time approved in accordance with Keystone RV's flat rate manual.
VCB: Vendor Charge Back item.
3 3201816A Decorative Wood 0.00 0.20 0.10 1 0.10 Complaint:TRIM IN FRONT STORAGE COMPARTMENT HAS COME OFF
Cause:unload compartment to get to trim climb in to compatment to restaple down trim strip,
Correction:unload compartment to get to trim climb in to compatment to restaple down trim strip,

4 2302218A Compartment Doc 0.00 0.20 0.20 1 0.20 Complaint:DOOR SIDE OUTSIDE KITCHEN DOOR LOCK

r paper claims ~~only~~ use one pre-authorization number per warranty claim for
iple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

e-Authorization

4/26/20
10:21:11

Job Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
								NEEDS ADJUSTED Cause: LOCK PLATE IS HITTING FRAME BEND IT OUT TO LOCK ON FRAME Correction: LOCK PLATE IS HITTING FRAME BEND IT OUT TO LOCK ON FRAME

3-Authorization number PA03413045

2.30

paper claims only use one pre-authorization number per warranty claim for
multiple copies of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim
form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the