

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70340
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11263 - 2023 CHEROKEE GREY WOLF 26DBH 4X4TCKB25PK086722

VIN: 4X4TCKB25PK086722 HIN:

SER#: 4X4TCKB25PK086722

Mileage: 0

Work Order Comp: 13 APR 23

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 12 APR 23

Inv #: 389722

WO # Job # Description JOB INFORMATION

70340 1 E3 CODE ON THERMOSTATE
E3 CODE ON THERMOSTATE MEANING COMMUNICATION ERROR REMOVED
THERMOSAT ALL THE WIRINES WERE TIGHT AND HOOKED UP PROPERLEY.
TRACED TO AC PLENUM REMOVED COVER AND FOUND WIRES UNCLIPPED. AS
SONN AS I CLIPPED BACK IN THEY WORKED FINE
E3 CODE ON THERMOSTATE MEANING COMMUNICATION ERROR REMOVED
THERMOSAT ALL THE WIRINES WERE TIGHT AND HOOKED UP PROPERLEY.
TRACED TO AC PLENUM REMOVED COVER AND FOUND WIRES UNCLIPPED. AS
SONN AS I CLIPPED BACK IN THEY WORKED FINE

70340 2 MAIN ENTRY DOOR HITTING
MAIN ENTRY DOOR WAS HITTING STRIKING PLATE AS STRIKING PLATE
NEEDED ADJUSTED. ADJUSTED STRIKE PLATE TO ALL MAIN ENTRY DOOR TO
SHUT RIGHT
MAIN ENTRY DOOR WAS HITTING STRIKING PLATE AS STRIKING PLATE
NEEDED ADJUSTED. ADJUSTED STRIKE PLATE TO ALL MAIN ENTRY DOOR TO
SHUT RIGHT

70340 3 DINETTE DRAWER NOT SHUTTING
DINETTE DRAWE NOT SHUTTING AS IT WAS NOT INSTALLED PROPPERLEY
REMOVED AND REINSTALLED PROPERLEY
DINETTE DRAWE NOT SHUTTING AS IT WAS NOT INSTALLED PROPPERLEY
REMOVED AND REINSTALLED PROPERLEY

70340 4 BTHROOM SINK DRAIN LOOSE NTO ATTACHED RIGHT
BATHROOM SINK WASNT ATTACHED RIGHT CAUSING LEAK WHEN RUNNING

Claim : 70340

 WO # Job # Description JOB INFORMATION

WATER. ALSO FOUND THE SEAL WAS NOT IN PLACE WHICH ISA WAHT CAUSED
 THE PIPE TO BE LOSE. REINSTALLED SEAL ANND INSTALLED DRAIN PIPE
 PROPERLEY THEN TESTED FOR LEAKS NO LEAKS FOUND AFTER FIX
 BATHROOM SINK WASNT ATTACHED RIGHT CAUSING LEAK WHEN RUNNING
 WATER. ALSO FOUND THE SEAL WAS NOT IN PLACE WHICH ISA WAHT CAUSED
 THE PIPE TO BE LOSE. REINSTALLED SEAL ANND INSTALLED DRAIN PIPE
 PROPERLEY THEN TESTED FOR LEAKS NO LEAKS FOUND AFTER FIX

70340 5 REAR SCREEN DOOR HITTING LATCH
 REAR SCREEN DOOR WAS HITTING LATCH AS THEY USED THE WRONG SCREWS,
 REMOVED OLD SCREWS AND INSTALL THE PROPPER ONES AND ADJUSTED
 LATCH AS WELL
 REAR SCREEN DOOR WAS HITTING LATCH AS THEY USED THE WRONG SCREWS,
 REMOVED OLD SCREWS AND INSTALL THE PROPPER ONES AND ADJUSTED
 LATCH AS WELL

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.40	160.00	64.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.30	160.00	48.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.40	160.00	64.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	160.00	32.00

Parts Total: 0.00
 Labour Total: 240.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 240.00

Customer Signature: _____

Date: _____