



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 70340

CUSTOMER WORK ORDER

WO #: 70340

Customer: 1000 - BASDEN'S

AMERICAN RV -

Tag:

Author: BH

Location: 0430 CHECK PREAUTH

Stock #: 11263

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE GREY WOLF 26DBH

Chassis #: 4X4TCKB25PK086722

Serial #: 4X4TCKB25PK086722

Mileage: 0

Licence:

Invoice #:

Date In: 12 APR 23

Promised:

Date Sched:

Completed: 13 APR 23

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDIED NEW TRAVEL TRAILER

CORRECTION: PDIED NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C
Z991	MISC LABOUR CODE (INTERNAL)	RAB	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: E3 CODE ON THERMOSTATE

CAUSE: E3 CODE ON THERMOSTATE MEANING COMMUNICATION ERROR REMOVED THERMOSAT ALL THE WIRINES WERE TIGHT AND HOOKED UP PROPERLEY. TRACED TO AC PLENUM REMOVED COVER AND FOUND WIRES UNCLIPPED. AS SONN AS I CLIPPED BACK IN THEY WORKED FINE

CORRECTION: E3 CODE ON THERMOSTATE MEANING COMMUNICATION ERROR REMOVED THERMOSAT ALL THE WIRINES WERE TIGHT AND HOOKED UP PROPERLEY. TRACED TO AC PLENUM REMOVED COVER AND FOUND WIRES UNCLIPPED. AS SONN AS I CLIPPED BACK IN THEY WORKED FINE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	64.00



Customer #: 1000



Subtotal for Job #1: 64.00

Job #2 - Warranty

COMPLAINT: MAIN ENTRY DOOR HITTING

CAUSE: MAIN ENTRY DOOR WAS HITTING STRIKING PLATE AS STRIKING PLATE NEEDED
ADJUSTED. ADJUSTED STRIKE PLATE TO ALL MAIN ENTRY DOOR TO SHUT RIGHT

CORRECTION: MAIN ENTRY DOOR WAS HITTING STRIKING PLATE AS STRIKING PLATE NEEDED
ADJUSTED. ADJUSTED STRIKE PLATE TO ALL MAIN ENTRY DOOR TO SHUT RIGHT

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	48.00
Subtotal for Job #2:			48.00

Job #3 - Warranty

COMPLAINT: DINETTE DRAWER NOT SHUTTING

CAUSE: DINETTE DRAWER NOT SHUTTING AS IT WAS NOT INSTALLED PROPERLEY REMOVED
AND REINSTALLED PROPERLEY

CORRECTION: DINETTE DRAWER NOT SHUTTING AS IT WAS NOT INSTALLED PROPERLEY
REMOVED AND REINSTALLED PROPERLEY

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00
Subtotal for Job #3:			32.00

Job #4 - Warranty

COMPLAINT: BTHROOM SINK DRAIN LOOSE NTO ATTACHED RIGHT

CAUSE: BATHROOM SINK WASNT ATTACHED RIGHT CAUSING LEAK WHEN RUNNING WATER.
ALSO FOUND THE SEAL WAS NOT IN PLACE WHICH ISA WAHT CAUSED THE PIPE TO BE LOSE.
REINSTALLED SEAL ANND INSTALLED DRAIN PIPE PROPERLEY THEN TESTED FOR LEAKS NO
LEAKS FOUND AFTER FIX

CORRECTION: BATHROOM SINK WASNT ATTACHED RIGHT CAUSING LEAK WHEN RUNNING
WATER. ALSO FOUND THE SEAL WAS NOT IN PLACE WHICH ISA WAHT CAUSED THE PIPE TO BE
LOSE. REINSTALLED SEAL ANND INSTALLED DRAIN PIPE PROPERLEY THEN TESTED FOR LEAKS
NO LEAKS FOUND AFTER FIX

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	64.00
Subtotal for Job #4:			64.00

Job #5 - Warranty

COMPLAINT: REAR SCREEN DOOR HITTING LATCH

CAUSE: REAR SCREEN DOOR WAS HITTING LATCH AS THEY USED THE WRONG SCREWS,
REMOVED OLD SCREWS AND INSTALL THE PROPPER ONES AND ADJUSTED LATCH AS WELL

CORRECTION: REAR SCREEN DOOR WAS HITTING LATCH AS THEY USED THE WRONG SCREWS,
REMOVED OLD SCREWS AND INSTALL THE PROPPER ONES AND ADJUSTED LATCH AS WELL

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	32.00

W/O: 70340

Customer #:
1000



W/O: 70340

Subtotal for Job #5: 32.00

Parts Total: 0.00
Labour Total: 240.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 240.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 13 Apr 2023



Customer #:
1000

