

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 70553
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER

Customer: 53576 - BRENT LOCKWOOD

Address: PO BOX 333
SANTA CLAUS, IN
47579

Phone: (317) 225-6325

Stock Number: 2022 CHEROKEE GREY WOLF

VIN:

HIN:

SER#: 5ZT2CKLB8NF002686

Mileage:

Work Order Comp: 08 MAY 23

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 02 MAY 23

Inv #: 390831

WO # Job # Description JOB INFORMATION

70553 6 THE FURTHEST USB PORT IN THE BUNK ROOM IS NOT WORKING.
REMOVED PORT AFTER TESTING AND INSTALLED NEW PORT

70553 1 THE TRIM THAT COVERS THE FRONT CORNER OF THE SIDING WHERE IT
MEETS THE NOSE CAP IS NOT QUITE LONG ENOUGH TO COVER THE END OF
THE SIDING PROPERLY. THE WAY IT IS ALLOWS WATER TO RUN IN.
CUSTOMER HAS COVERED AREA WITH SILICONE, BUT THE SILICONE IS NOT
HOLDING.
CUT OFF DOOR SIDE TRIM TO LOOK RIGHT. SILICONED AREAS THAT WERE
MISSING SILICONE. AND THE AREA HE WAS TALKING ABOUT IS FINE.
THERE IS NO WAY WATER CAN GET IN UNIT.

70553 2 THE BATHROOM DOOR DOES NOT CLOSE PROPERLY. THE GAP AT THE TOP OF
THE DOOR IS QUITE A BIT DIFFERENT THAN THE GAP AT THE BOTTOM OF
THE DOOR.
REMOVED DOOR. REMOVED BOTH PLASTIC COVERS. REMOVE WALL PANELS.
REMOVE STRIKE FRAME AND TRIED TO ADJUST IT ON THE BOTTOM. DIDNT
WORK. REMOVED HINGE FRAME AND MOVED OVER THE TOP. STILL DIDNT
WORK .REMOVE BOTH FRAMES AND STARTED OVER. SQUARED UP HINGE
FRAME. RIP STRIKE FRAME TO MOVE OVER AND FIT. TESTED DOOR. PUT
PANELS BACK. PUT PLASTIC COVERS BACK. HANG DOOR AND TEST. FILL
HOLES WITH PUTTY

70553 3 LOOK AT AREA FROM UNDER KITCHEN DINING BENCH GOING INTO THE
STORAGE AREA BELOW THE BUNK HOUSE. CUSTOMER NOTICES A 2' GAP AND
POINTED OUT TO WRITER THAT IT WOULD BE AN IDEAL LOCATION FOR A

Claim : 70553

 WO # Job # Description JOB INFORMATION

 SNAKE TO GET IN AND THEN COME INSIDE TO THE KITCHEN AREA.
 Stapled a black baton strip on the lower part of the bench seat.

70553 4 THE DOOR SIDE STORAGE COMPARTMENT HAS QUITE A GAP BETWEEN THE
 DOOR AREA AND THE BODY SEE WRITER FOR DETAILS.
 CUT PANEL AND SCREWED DOWN. PUT TAPE ON IT

 Part No Job# Description PARTS Qty Price Total

 F100130007/FR 6 CHARGER, DUAL USB (2 PORTS) 5V BL 1.00 3.74 3.74

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.50 160.00 80.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 1.50 160.00 240.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 160.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.10 160.00 16.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.20 160.00 32.00

 Excode Job# Description EXTRAS Qty Price Total

 SS 1 SHOP SUPPLIES 1.00 3.00 3.00

Parts Total: 3.74
 Labour Total: 400.00
 Sublet Total: 0.00
 Extras Total: 3.00

>>>>> Claim Total: 406.74

Customer Signature: _____

Date: _____