

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1584582
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT3SR2B2N6111193
USA		CHASSIS VIN	

Labor rate: \$160.00

OWNER INFORMATION

HEATH M BALTHUS

8700 BOOKER
Evansville, IN 47720
USA

MILEAGE	0
SITE/WAREHOUSE	062 / 062C
ITEM #	SRF37FLL-C
DEALER RO #	70912
CLAIM START DATE	06/27/2023
CLAIM END DATE	01/01/1900

Retail Date of Purchase 05/26/2023

WARRANTY EXPIRATION DATE 05/26/2024

Claim Line Details

Labor

Line# 1	Operation Code 30-102-01-00-001118	Operational Description Miscellaneous Interior Trim, each - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-06-27 11:32:48 :: TRIM FELL OFF ON CABINET UNDER CONTROL CENTER REPAIRED AREA WITH MATCHING TRIM TAPE		
Model #	Dlr Sub Hrs	0.10
Serial #	Appr Hrs	0.10
	Sub Labor Amt	\$16.00
	Appr Labor Amt	\$16.00

Notes

Labor

Line# 2	Operation Code 30-102-01-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2023-06-27 11:34:41 :: FRIDGE LATCH FELL OFF AND HIT CABINET AND DAMAGED CABINET THE ONE RIGHT NEXT TO IT I GLUED THE SNAP FOR THE STRAP BACK TO THE TOP OF THE FRIDGE. I SNAPPED THE LOCKING STRAP BACK ON TOP OF FRIDGE. I TOUCHED UP THE SCRATCH ON THE FRIDGE DOOR. I REMOVED THE CABINET TRIM AND REPAIRED WITH MATCHING TRIM TAPE, REINSTALLED CABINET CORNER TRIM.		
Model #	Dlr Sub Hrs	0.20
Serial #	Appr Hrs	0.20
	Sub Labor Amt	\$32.00
	Appr Labor Amt	\$32.00

Notes

Submitted	Labor Amt	\$48.00	Approved	Labor Amt	\$48.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$48.00		Total	\$48.00

DEALER
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

All repairs described have been inspected and are satisfactory.