

e-Authozization

7/5/20
03:53:26 PM

3-Authozization number PA03475627 Reference no: 70921 Status: Approved Approved by stept Approved date 7/5/2023

ricing Name Address VIN Retail sold on

34	Basden's American RV	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	4YDFCGN2XP2508802					
lu Root e operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	2300114A Entrance Door - l-	0.00	0.20	0.20		1	0.20	Complaint:ENTRY DOOR FRAMEW IS BENT Cause:INSTALLE WRONG Correction:ADJUSTED DOOR AND GOT DOOR FRAME STRAIGHT AND WORKING RIGHT
KRV – Labor time approved in accordance with Keystone RV's flat rate manual.								
2	4120614A Furnace - Suburb.	0.00	0.10	0.10		1	0.50	Complaint:OUT SIDE FURANCE COVER NOT INSTALLED ALL THE WAY Cause:INSTALL ISSUE NOT LONG ENOUGH SCREWS Correction:I got longer screws and put them in,
KRV – REPAIR ONLY approved.								
3	4206316A Television - Repai	0.00	0.75	0.30		1	0.30	Complaint:There was no cable reception in the bedroom or outside area. Cause:FOUND LOOSE CABLES Correction:Check The Wire linked inside of the coax kept looking for the problem. I found the problem was in the outside. Main cable bank, the orange wire. And the Gray wire on the coax was both loose from the bank. The orange wire fed the outside TV. The Gray wire fed the inside TV.
KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.								
4	3201816A Decorative Wood	0.00	0.10	0.10		1	0.10	Complaint:There was trim that was falling down in the kitchen Cause:STAPLED IT BACK UP Correction:STAPLED IT BACK UP
KRV – Labor time approved in accordance with Keystone RV's flat rate manual.								
5	3300516A Blind - Vertical - F	0.00	0.10	0.10		1	0.20	Complaint:Up the blind above the low seat would not stay down. Cause:I had to adjust the rollers on Ton both sides to tighten it

r paper claims only use one pre-authozization number per warranty claim for
iple a copy of this pre-authozization to a warranty claim form. Fill out the header information and the parts section on the claim
m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the

Pre-Authorization

7/5/20
03:53:26 PM

Job Root Job operation of	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
Correction: I had to adjust the rollers on Ton both sides to tighten it up.								
KRV - REPAIR ONLY approved.								
Pre-Authorization number PA03475627				0.80				

paper claims ~~only~~ use one pre-authorization number per warranty claim for

multiple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the