



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71319
Promised Date:
24 AUG 23



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 71319

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0911 SEE IF PARTS ARE HERE
YET

Stock #: 11123
Stock Desc: 2024 5W KEYSTONE
COUGAR SPORT 2100RK
Chassis #: 4YDFCGJ21R2501195
Serial #: 4YDFCGJ21R2501195
Mileage: 0
Licence:

Invoice #:
Date In: 01 AUG 23
Promised: 31 AUG 23
Date Sched:
Completed: 31 AUG 23
Warr. Date:

Job #BUNKHOUSE - Internal

COMPLAINT: Transferred to BAS*71568 on 29 AUG 23
Estimate amount was 0.00
PRE DELIVERY INSPECTION NEW BUNKHOUSE

CAUSE: .

CORRECTION: I did the PDI for new cougar fifth wheel. I made 2 battery cables for the battery box. On the delivery inspection, there was 2 notes about cabinet doors. One of the cabinet doors on the inside were the latch screws to the door. The wood was cracked a little bit. I filled the crack with wood above. The kitchen sink was not closing properly. So I tried to tweak the door a little bit while doing that. I broke the cabinet door I took measurements. I made a purchase order for a new cabinet, Thor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Other Services

Code	Description	Qty	Price	Total
LPG	LP GAS	0.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #BUNKHOUSE: 0.00

Job #1 - Warranty

COMPLAINT: CABINET DOOR ABOVE THE KITCHEN SINK WILL NOT LATCH

CAUSE: THE DOOR WOULD NOT LATCH PROPERLY, IT WASNT HITTING THE CABINET AT THE BOTTOM BUT WAS AT THE TOP. I TRIED TO TWEAK THE DOOR A LITTLE, WELL I BROKE THE DOOR. DOOR SIZE IS 13 3/4 X 21 3/4 WHITE

CORRECTION: REMOVED CABINET DOOR AND MASURED HINGES AND PREDRILLED HOLES AND PLACED HINGES ON NEW CABINET DOOR AND REMOUNDED DOOR AND AJUSTED GAP

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JG	32.00
Z990	MISCELLANEOUS REPAIR	DWW	0.00

Subtotal for Job #1: 32.00

Job #2 - Warranty

COMPLAINT: THE SHORE CORD LIGHTS DO NOT WORK





CORRECTION: THE SHORE THAT CAME WITH THE UNIT THE LIGHTS ON IT DOES NOT WORK.
NEED NEW CORD. 30FT 50 AMP FURRION CORD WITH LIGHTS.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	DWW	16.00

Parts				
Part #	Description	Qty	Price	Total
708948	Cord - Shore/Power - 50A - 30' - w/T	1.00	196.65	196.65

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-CORD	1.00	26.73	26.73

Subtotal for Job #2: 239.38

Job #3 - Warranty

COMPLAINT: CABINET DOOR NEAR THE TV HAS A LITTLE DAMAGE IN THE DOOR

CORRECTION: THE CABINET DOOR TO THE LEFT OF THE TV ON THE INSIDE WHERE THE LATCH WAS SCREWED TO THE DOOR HAD A SMALL STRESS CRACK IN IT. I FILLED THE CRACK WITH WOOD PUTTY. I DID NOT GET PICS SORRY.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	DWW	32.00

Parts				
Part #	Description	Qty	Price	Total
708573	Cabinet - Door - FPSQ - 14" x 22" -	1.00	32.53	32.53

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-CAB DOOR	1.00	31.19	31.19

Subtotal for Job #3: 95.72

Parts Total: 229.18
Labour Total: 80.00
Sublet Total: 0.00
Extras Total: 57.92
WORK ORDER TOTAL: 367.10

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 09 Sep 2023

