



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 71367
Promised Date:
24 AUG 23



Customer #: 40167
MCCORKLE, STEVEN W.



CUSTOMER WORK ORDER

WO #: 71367 (Appointment Date: 07 AUG 2023 - Time: 09:00am)

Customer: 40167 - MCCORKLE,
STEVEN W. - 618-262-3717

Tag: IN PREAUTH

Author: BJW

Location: 0828 CHECK WORK WITH
BILL

Stock #: 11195

Stock Desc: (11195) 2022 ALLIANCE RV
PARADIGM 295MK

Chassis #: 7M5FP3421NB201643

Serial #: 7M5FP3421NB201643

Mileage:

Licence:

Invoice #:

Date In: 07 AUG 23

Promised: 31 AUG 23

Date Sched:

Completed: 25 AUG 23

Warr. Date: 24 MAY 23

Job #1 - Warranty

COMPLAINT: BEDROOM AC WILL NOT RUN ON LOW FAN. FAN WILL RUN ON ALL OTHER
SETTINGS AND THE COMPRESSOR RUNS.

CAUSE: .

CORRECTION: Found low speed wire for fan disconnected. Pulled plenum down. And reconnected wire
and tested operation.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	144.00

Subtotal for Job #1: 144.00

Job #2 - Warranty

COMPLAINT: CHECK THAT ANTENNA IS HOOKED UP FOR THE RADIO, CUSTOMER STATES HE
DOES NOT GET ANY STATIONS.

CAUSE: .

CORRECTION: Found antenna wire disconnected. I reconnected and tested and had several channels.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	32.00

Subtotal for Job #2: 32.00

Job #3 - Warranty

COMPLAINT: WATER PRESSURE IS WEAK AT THE KITCHEN SINK. THIS IS THE CASE WHEN
CUSTOMER IS RUNNING OFF OF FRESH TANK OR HOOKED TO CITY WATER.

CAUSE: The aerator in the faucet was full of plastic.

CORRECTION: Took apart and cleaned out the plastic.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	48.00

Subtotal for Job #3: 48.00

Job #4 - Warranty

COMPLAINT: THE WEIGHT FOR THE FAUCET PULL OUT HOSE FELL OFF. CAN IT BE ZIPPED TIED



BACK INTO PLACE

CAUSE: .won't stay on hose

CORRECTION: Secured with zip tie.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	16.00

Subtotal for Job #4: 16.00

Job #5 - Warranty

COMPLAINT: CUSTOMER WAS UNABLE TO GET THE INVERTER TO POWER UP AT HIS HOME. CUSTOMER THEN TRAVELED TO HIS DESTINATION AND THE INVERTER POWERED UP. CUSTOMER IS CONCERNED THAT THERE MAY BE A LOOSE CONNECTION.

CAUSE: Push button from inside or out and it will not turn on.

CORRECTION: INSTALLED NEW INVERTER AND TESTED OPERATION.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	160.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00

Parts

Part #	Description	Qty	Price	Total
12123	12123 Inverter - 2000 Watt - 2KW PD1600 Series	1.00	553.99	553.99

Other Services

Code	Description	Qty	Price	Total
FRT	UPS - INVERTER	1.00	24.02	24.02

Subtotal for Job #5: 738.01

Job #6 - Warranty

THE INVERTER WE JUST INSTALLED HAS FAILED GIVING A E5 CODE

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	144.00
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	96.00

Subtotal for Job #6: 240.00

Parts Total: 553.99
Labour Total: 640.00
Sublet Total: 0.00
Extras Total: 24.02
WORK ORDER TOTAL: 1,218.01

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 Aug 2023

W/O: 71367
Promised Date: 31 AUG 23



Customer #: 40167
MCCORKLE, STEVEN W.

