

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1674096
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAEC9RK006713
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$160.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BHX
JAMES T WAHNSIEDLER		DEALER RO #	71594
120 N MARINE AVE		CLAIM START DATE	09/13/2023
Evansville, IN 47712		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	09/08/2023	WARRANTY EXPIRATION DATE	09/08/2024

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-09-13 11:21:41 :: WATER PUMP NEEDS GROUNDING CAUSES LIGHTS TO FLICKER Water pump doesn't have a good ground Cut then negative side of water pump wires the spliced in wire to ground to frame. Took pictures			
	Model #	Dlr Sub Hrs	0.30	Sub Labor Amt \$48.00
	Serial #	Appr Hrs	0.30	Appr Labor Amt \$48.00
	Notes			
	AUTHORIZED AS REQUESTED			

Labor

Line# 2	Operation Code	Operational Description		
	20-73-15-00-000745	Wheel Well Trim - Exterior/Fender Skirts/Wheel Well/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2023-09-13 11:24:27 :: RIGHT SIDE FENDER LINER IS NOT COMPLETE Fender Remove long leg fender. Cut back siding . Put fender back. Tape off and siliconed. Also put extream tape over exsposed wood.			
	Model #	Dlr Sub Hrs	0.20	Sub Labor Amt \$32.00
	Serial #	Appr Hrs	0.20	Appr Labor Amt \$32.00
	Notes			

Submitted	Labor Amt	\$80.00	Approved	Labor Amt	\$80.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$80.00		Total	\$80.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.