



Warranty Authorization Form

Date: 2/9/2024

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200

General Information

Pre-Auth #: 56775 Unit: 7M5FV4432NA006354
Series: Valor Model: 2022VAL41V15
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22308 ENTRANCE DOOR - SCREEN DOOR - REPAIR Fault Code: MISALIGNED
(photos of defect and door tag)

Serial #:

Model #:

Notes:

Problem: SCREEN DOOR NOT CONNECTED AT TOP, IT STICKS WHEN USING UNIT HAS
BEEN WINTERIZED PER CUSTOMER

Time Requested: .2

Time Allowed: .2

Cause: screen door

Sublet Repairs: 0.00

Remedy: took out top screws because they were stripped, installed bigger screws to
tighten, screen was hitting on top, adjusted screen so it would not hit.

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: COMPONENT FAILURE

Serial #:

Model #:

Notes:

Problem: TRIM NEEDS FIXED. THERE ARE A COUPLE OF PIECES AROUND THE CEILING
AND ONE ON THE SIDE THAT ARE COMING LOOSE. THESE ARE IN THE LIVING AREA, BUT
THEY ARE NEAR THE GARAGE SECTION.

Time Requested: .8

Time Allowed: .8

Cause: trim loose

Sublet Repairs: 0.00

Remedy: stapled trim back in place by ceiling, in 2 places, then took off trim on slideroom and
stapled back in place then put corner piece back in place.

Part Return Req: No

Status: Approved