

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1842074
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CALB5RU043045
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT221MKE-8
		DEALER RO #	72977
		CLAIM START DATE	03/07/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-103-24-00-001125	Linoleum - Interior/Flooring/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-07 15:46:11 :: SMALL IN FLOOR IN FRONT OF SLIDE OUT 2 holes in the floor in front of the Repai 2 holes in the floor in front of the sofa in the slide. Patched holes in the floor and filed sharp edges off of trim work next to the sofa. Pictures taken			
Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$85.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$85.00
	Notes	AUTHORIZED AS REQUESTED.		

Labor

Line# 2	Operation Code	Operational Description		
	30-101-02-00-001076	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-07 15:47:30 :: BATHROOM DOOR HITTING FRAME Bathroom door hitting frame Adjust door latch and catch, also tighten door handle			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-07 15:48:30 :: ENTRY DOOR NEEDS ADJUSTING Entry door needs adjusted Adjust door latch and door catch, door opens and closes just fine now			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$51.00
	Notes			

Labor

Line# 4	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-03-07 15:49:25 :: RIGHT REAR SIDE MARKER LIGHT OUT Right rear side marker light oit. Removed light and found no power wire attached, no wire ran to the light. Fished new wire to the light from the right tail light wiring. Light operates as it should.			
Model#	Dlr Sub Hrs	2.50	Sub Labor Amt	\$425.00

Serial#

Appr Hrs

2.50

Appr Labor Amt \$425.00

Notes

THE PHOTO PROVIDED SHOWS THE LIGHT WORKING. PLEASE SUBMIT MORE PHOTOS.
SORRY THE TABLET LOST THE PHOTOS THE WIRE WAS NOT CONNECTED IN THE PIC
AUTHORIZED AS REQUESTED.

Submitted

Labor Amt	\$595.00
Parts & Freight	\$0.00
Total	\$595.00

Approved

Labor Amt	\$595.00
Parts & Freight	\$0.00
Total	\$595.00

DEALER**DATE****SIGNATURE**

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER**DATE****SIGNATURE**

All repairs described have been inspected and are satisfactory.