

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1854978
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARBXR030510
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	205 / 205
Labor rate:	\$170.00	ITEM #	ACAT263BHCKLE
OWNER INFORMATION		DEALER RO #	73059
SCOTT D BUEDEL		CLAIM START DATE	03/20/2024
10501 DENZER RD		CLAIM END DATE	01/01/1900
Evansville, IN 47720			
USA			
Retail Date of Purchase	03/16/2024	WARRANTY EXPIRATION DATE	03/16/2025

Claim Line Details

Labor

Line# 1

Operation Code

SB-456-01-00-004506

Operational Description

51-1722 – ROOF MOUNT SOLAR INLET (AURORA & CATALINA) - INSPECTION AND PERFORM REMEDY - Technical Service Bulletin/Sealant/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-03-20 09:23:39 :: ROOF MOUNT SOLAR INLET MIGHT BE CRACKED solar inlet PULLED SOLAR MOUNT AND REPLACED WITH NEW

Model#

Dlr Sub Hrs

0.50

Sub Labor Amt

\$85.00

Serial#

Appr Hrs

0.50

Appr Labor Amt

\$85.00

Notes

AUTHORIZED AS REQUESTED

Labor

Line# 2

Operation Code

10-1-01-00-000047

Operational Description

Axle Dust, Grease, or Bearing Cap - Frame & Chassis/Axles, Suspension/ Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-03-20 09:25:47 :: LR WHEEL MAKING NOISE wheel making noise took off cap and cap for spindle was off,took off wheel and had to replace cap because it would not stay on,installed wheel back in place and tourqued down.

Model# NA

Dlr Sub Hrs

0.20

Sub Labor Amt

\$34.00

Serial# NA

Appr Hrs

0.20

Appr Labor Amt

\$34.00

Notes

Labor

Line# 3

Operation Code

60-136-15-00-001499

Operational Description

Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2024-03-20 09:27:00 :: THE WATER PUMP WILL NOT PULL WATER OUT OF THE TANK no water to pump chased line through floor went underneath and cut underbelly in 2 places and found kink in line, took pictures, cut both lines where kink was and reused elbow, cut hard line back more to match up with elbow to line, crimped elbow on both lines and tested all good and no leaks, next taped up underbelly.

Model#

Dlr Sub Hrs

0.70

Sub Labor Amt

\$119.00

Serial#

Appr Hrs

0.70

Appr Labor Amt

\$119.00

Notes

AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$238.00
	Parts & Freight	\$0.00
	Total	\$238.00

Approved	Labor Amt	\$238.00
	Parts & Freight	\$0.00
	Total	\$238.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.