

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1891440
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAECXRK006719
USA		CHASSIS VIN	
		MILEAGE	0

Labor rate:	\$170.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT164BHX
AMANDA L PARKE		DEALER RO #	73401
692 S DEER HAVEN DR		CLAIM START DATE	04/22/2024
Princeton, IN 47670		CLAIM END DATE	01/01/1900
USA			

Retail Date of Purchase	10/07/2023	WARRANTY EXPIRATION DATE	10/07/2024
-------------------------	------------	--------------------------	------------

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description	
SB-456-01-00-004506	51-1722 – ROOF MOUNT SOLAR INLET (AURORA & CATALINA) - INSPECTION AND PERFORM REMEDY - Technical Service Bulletin/Sealant/Replace/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-04-22 11:01:25 :: ROOF MOUNT SOLAR INLET COULD BE CRACKED AND NEED TO BE REPLACED Outlet Cut alpha off old one. Wire up new outlet. Put alpha on.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.50	\$85.00
Serial#	Appr Hrs	Appr Labor Amt
	0.50	\$85.00
Notes		
AUTHORIZED AS REQUESTED		

Labor

Line# 2

Operation Code	Operational Description	
RC-003-22-00-004526	24V254, 2024-214 - CHARGE LINE OVERCURRENT PROTECTION - INSPECTION AND REMEDY - Recall/Electrical/Rewire/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-04-22 11:02:41 :: CHARGE LINE OVERCURRENT PROTECTION Recall Removed upper wire and put on lower part of fuse. Took pics		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
Notes		
AUTHORIZED AS REQUESTED		

Labor

Line# 3

Operation Code	Operational Description	
40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/Electrical	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2024-04-22 11:03:23 :: OUTLET CAME OUT OF THE WALL IN FRONT LEFT Outlet Removed outlet and moved up and fasten. Took pics		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$51.00
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$51.00
Notes		

Labor

Line# 4

Operation Code	Operational Description	
40-106-01-00-001263	Battery Box or Tray - Electrical/12 Volt Exterior/Replace/No Tread Code	
Complaint, Cause, Correction		

Original Note : bhoffman@americanrvcenter.com, 2024-04-22 11:04:41 :: BREAKER BOX LID WONT STAY SHUT
Clip Replaced clip on door. Took pics

Model#	Dir Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00

Notes
WILL NEED PHOTO SHOWING LID.
PHOTOS ADDED
AUTHORIZED AS REQUESTED

Submitted	Labor Amt	\$187.00
	Parts & Freight	\$0.00
	Total	\$187.00

Approved	Labor Amt	\$187.00
	Parts & Freight	\$0.00
	Total	\$187.00

DEALER _____ **DATE** _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE

All repairs described have been inspected and are satisfactory.