



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73476
Promised Date:
18 MAY 24

CUSTOMER WORK ORDER

WO #: 73476

Customer: 54758 - HALL, MICHAEL S. -
812-827-1240

Tag:

Author: BH

Location: 0525 CHECK PREAUTH

Stock #: 11377

Stock Desc: 2024 TT KEYSTONE

SPRINGDALE 260BHC

Chassis #: 4YDTSGL23R7104318

Serial #: 4YDTSGL23R7104318

Mileage: 0

Licence:

Invoice #:

Date In: 24 APR 24

Promised: 18 MAY 24

Date Sched:

Completed: 22 MAY 24

Warr. Date: 18 MAY 24

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 4 HR PDI

CAUSE: PDINTT PDI NEW TRAVEL TRAILER

CORRECTION: Moved unit into shop from sales lot. Installed battery box and new battery. Tied up all wires to battery. Removed battery disconnect switch from mounting and tightened battery cables on back of switch. Remounted Battery switch on tongue of unit. Filled LP tanks and installed on frame. Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 75 psi. Checked power cord. Checked roof and awning. Operated Electric stab jacks. Checked entrance door and all compartment doors. Checked all interior lights. Checked converter output. Checked all electrical outlets and GFCI outlets. Checked all USB outlets. Checked all windows and blinds. Filled fresh water tank. Flushed antifreeze from water pump. Checked all water lines and faucets for leaks. Performed LP drop test and set LP pressure at 10 in.wc. Removed winterized stickers. Filled all holding tanks and checked monitor panel. Checked all appliances, including Refrigerator. Range, Microwave Furnace, Air Conditioner and Water Heater. Checked TV Antenna with test TV at all antenna connections.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Drained all holding tanks. Retracted electric stab jacks. Applied all company decals. Moved unit to wash bay area.

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 54758
HALL, MICHAEL S.





PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
10-7090	1pc 1/2" PLUG CAP	2.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 10K E2 EQUALIZER HITCH

CORRECTION: Assembled hitch brackets and mounted on frame of unit. Relocated Chassis ground screw to make way for hitch bracket.

SETUP HITCH HIGHT AND HOOKED UP TO TRAILER. ADJUSTED HITCH AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #BCWT - Internal

COMPLAINT: BRAKE CONTROL & WIRING - PICKUP TRUCK ONLY

CORRECTION: INSTALLED BRAKE CONTROL AND REPAIRED WIRING. THE GROUND WIRE FOR THE 7-WAY NEEDED TO BE FIXED. IT WAS NO LONGER GROUNDING AS IT SHOULD. I ADDED A GROUND WIRE AND NOW THE 7-WAY IS WORKING AS IT SHOULD.

Labor

Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C
19-0938	9 WAY CONNECTOR - BRACKET	1.00	N/C	N/C
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C
17-0081	#51120 BRAKE CONTROL	1.00	N/C	N/C
81783	81783 92-19	1.00	N/C	N/C
	FORD/MERCURY/LINCOLN			
FOAZ14N089A	FORD RELAY	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BCWT: 0.00

Job #DELUXE - Internal

COMPLAINT: DELUXE STARTER KIT

CORRECTION: PUT IN UNIT



W/O: 73476
Promised Date: 18 MAY 24



Customer #: 54758
HALL, MICHAEL S.



Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #1 - Warranty

COMPLAINT: THE GREASE CAP ON THE ROADSIDE FRONT AXLE IS COMING OFF.

CAUSE: GREASE CAP ON THE ROADSIDE FRONT AXLE IS COMING OFF

CORRECTION: Removed tire and wheel from axle. Put grease cap back on axle. Remounted tire and wheel. Torqued lug nuts.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00
Subtotal for Job #1:			34.00

Job #2 - Warranty

COMPLAINT: SHOWER SURROUND NEEDS RESEALING AT TOP

CAUSE: SHOWER SURROUND NEEDS RESEALING AT TOP (NOTED AT DELIVERY)

CORRECTION: Resealed Shower surround at top with clear silicone.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	DKM	34.00
Subtotal for Job #2:			34.00

Parts Total:	0.00
Labour Total:	68.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	68.00

Thank you for being a valued customer. We appreciate your business.
All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 May 2024

