



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73502
Promised Date:
20 APR 24



Customer #: 54716
CRANEY, MIKE P



CUSTOMER WORK ORDER

WO #: 73502

Customer: 54716 - CRANEY, MIKE P -
812-455-2931

Tag:

Author: BH

Location: 0506 CHECK PREAUTH

Stock #: 11265

Stock Desc: 2023 TT FOREST RIVER

CHEROKEE WOLF PUP 16CW

Chassis #: 5ZT2CKEC3PY029338

Serial #: 5ZT2CKEC3PY029338

Mileage:

Licence:

Invoice #:

Date In: 27 APR 24

Promised: 30 APR 24

Date Sched:

Completed: 30 APR 24

Warr. Date: 30 APR 24

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: FPDINTT FINAL PDI ON NEW TRAVEL TRAILER

CORRECTION: Checked all exterior lights and brakes. Checked lug nuts and set tire pressure at 80 psi. Operated all stab jacks. Checked power cord. Checked converter output. Checked roof. Checked awning. Checked all interior lights. Flushed all antifreeze from water lines and faucets. Water faucet in bathroom leaking on both sides. Performed LP drop test and set LP pressure at 10 in.wc. Drained all holding tanks. Checked all appliances. Checked TV Antenna with test TV. Moved unit to washbay area.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	DKM	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 10K E2 EQUALIZER HITCH

CORRECTION: Assembled hitch brackets and mounted on frame of unit.
CHANGED BALL TO A 2" BALL. SETUP HITCH HIGHT AND HOOKED UP TO TRAILER. ADJUSTED HITCH AS NEEDED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
21200	21200 REDUCER BUSHING 1 1/4 IN TO 1 IN YELLOW ZINC BULK	1.00	N/C	N/C
40066	PACKAGED HITCH BALL6K 2IN X 1IN X 2 1/8IN	1.00	N/C	N/C



Subtotal for Job #E2: 0.00

Job #JACK - Internal

COMPLAINT: INSTALL ELECTRIC TONGUE JACK

CAUSE: JACK INSTALL ELECTRIC TONGUE JACK

CORRECTION: Removed manual tongue jack from unit. Installed new electric tongue jack. Connected wiring with inline fuse to battery. Checked operation.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
3291	3500# STROMBERG ELEC JACK -BULK	1.00	N/C	N/C

Subtotal for Job #JACK: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT

Parts

Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C

Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: BATHROOM FAUCET LEAKS

CAUSE: BATHROOM FAUCET LEAKS

CORRECTION: Cone washer missing from both hot and cold connections on bathroom faucet. Replaced missing cone washers in both hot and cold faucets in bathroom.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	68.00

Parts

Part #	Description	Qty	Price	Total
10-7150	CONE WASHER SWIVEL SEAL	2.00	0.18	0.36

Subtotal for Job #1: 68.36

Parts Total:	0.36
Labour Total:	68.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	68.36

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 73502
Promised Date: 30 APR 24



Customer #: 54716
CRANEY, MIKE P

