



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 73589



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 73589

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0515 CHECK PREAUTH

Stock #: 11389

Stock Desc: 2024 TT COACHMEN
CATALINA SUMMIT SERIES 261BHS

Chassis #: 5ZT2CARB0RU043610

Serial #: 5ZT2CARB0RU043610

Mileage: 0

Licence:

Invoice #:

Date In: 07 MAY 24

Promised:

Date Sched:

Completed: 14 MAY 24

Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER - 4 HR PDI

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C
Z991	MISC LABOUR CODE (INTERNAL)	DKM	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
10-1211	20183 3-PK 1" HOSE FILTERS	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SCREEN DOOR IS TORN. NOTED AT DELIVERY

CAUSE: SCREEN MATERIAL TORN ON SCREEN DOOR (NOTED ON DELIVERY)

CORRECTION: Removed screen door from entrance door. Removed torn screen material from bottom panel. Installed new screen material in bottom panel of screen door. Treimmed off excess material. Reinstalled screen door on entrance door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00

Subtotal for Job #1: 34.00

Job #2 - Warranty

COMPLAINT: BOTTON SHEET METAL SUPPORTS NOT ATTACHED ON CURBSIDE

CAUSE: BOTTOM SHEET METAL SUPPORTS NOT ATTACHED ON CURBSIDE REAR (NOTED ON DELIVERY)

CORRECTION: Supports were attached on one end to frame but not on other end to bottom sheet metal. Bent supports to fit and attached to vbottom sheet metal with matching screws.



Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	51.00
Subtotal for Job #2:			51.00

Job #3 - Warranty

COMPLAINT: FREEZER DOOR ON REFRIDGERATOR WONT CLOSE

CAUSE: FREEZER DOOR ON REFRIGERATOR WONT CLOSE.

CORRECTION: Freezer door is hitting screws that mount safety latch. Loosened mounting and straightened latch. Freezer still hitting. Bent latch down a little. Now door closes all the way anddoesnot hit screw.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DKM	34.00
Subtotal for Job #3:			34.00

Parts Total:	0.00
Labour Total:	119.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	119.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 14 May 2024

Customer Signature : _____

W/O: 73589



Customer #: 1000
BASDENS AMERICAN RV,

