



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 73612  
Promised Date:  
24 MAY 24

### CUSTOMER WORK ORDER

WO #: 73612 (Appointment Date: 09 MAY 2024 - Time: 09:00am)

Customer: 54121 - SHARP, ROGER -  
270-929-3551

Tag: BJ - REFER ORDERED. 5-14-24

Author: BJW

Location: 0521 BH TO CLOSE

Stock #: 11282

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAECXRK006817

Serial #: 5ZT2CAECXRK006817

Mileage: 0

Licence:

Invoice #:

Date In: 09 MAY 24

Promised: 31 MAY 24

Date Sched:

Completed: 22 MAY 24

Warr. Date: 20 OCT 23

#### Job #1 - Warranty

COMPLAINT: CUSTOMER NOTICED THAT IT DIDN'T SEEM LIKE THE REFRIGERATOR WAS COOLING PROPERLY AT THE END OF CAMPING SEASON LAST FALL. CUSTOMER TOOKE UNIT CAMPING THIS SPRING ON A MONDAY. BY WEDNESDAY, THE REFRIGERATOR AND FREEZER STOPPED COOLING AL TOGETHER.

CAUSE: ref not cooling

CORRECTION: plugged camper in and letting ref run, tested voltage and it has 13.50 and is running, will wait to see temp in a few hours.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00

#### Parts

Part #	Description	Qty	Price	Total
F100463470	REFER, 3.3 CU FT 12V BLACK IRV LH iR	1.00	376.66	376.66

#### Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT-REFER	1.00	229.28	229.28

**Subtotal for Job #1: 690.94**

#### Job #2 - Warranty

COMPLAINT: THE DOOR SIDE FRONT RUNNING LIGHT IS MISSING.

CAUSE: missing lens

CORRECTION: took off old light and wired in new light and tested and sealed.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

#### Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 54121  
SHARP, ROGER



210626 MCL0032ABS 1-LED AMBER MARKER LIGHT 1.00 3.83 3.83

Subtotal for Job #2: 37.83

Job #24V254 - Warranty

COMPLAINT: 24V254 CHARGE LINE OVERCURRENT PROTECTION

CAUSE: recall 24v254 charge line overcurrent protection

CORRECTION: took pictures and changed wires to figure 2 and sprayed with battery protector

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	34.00

Subtotal for Job #24V254: 34.00

Job #51-1722 - Warranty

COMPLAINT: 51-1722 ROOF MOUNT SOLAR INLET MIGHT BE CRACKED

CAUSE: recall 51-1722 solar inlet

CORRECTION: cut away dicor and pulled screws out and took off sealant,wired up new inlet and screwed down,then put dicor around it.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	85.00

Subtotal for Job #51-1722: 85.00

Parts Total:	380.49
Labour Total:	238.00
Sublet Total:	0.00
Extras Total:	229.28
<b>WORK ORDER TOTAL:</b>	<b>847.77</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 22 May 2024

W/O: 73612  
Promised Date: 31 MAY 24



Customer #: 54121  
SHARP, ROGER

