

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	1940238
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	5ZT2CAUB8RX031193
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$170.00	<b>SITE/WAREHOUSE</b>	205 / 205
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	ACAT293TQBSCKLE
BRENT A MARTINDALE		<b>DEALER RO #</b>	73773
7640 SO CO RD 875 E		<b>CLAIM START DATE</b>	06/04/2024
Carlisle, IN 47838		<b>CLAIM END DATE</b>	01/01/1900
USA			
<b>Retail Date of Purchase</b>	05/30/2024	<b>WARRANTY EXPIRATION DATE</b>	05/30/2025

## Claim Line Details

### Labor

<b>Line# 1</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-06-04 13:08:44 :: TRIM LOOSE INSIDE ON BOTH SIDES OF ENTRANCE DOOR TRIM LOOSE INSIDE ON BOTH SIDES OF ENTRANCE DOOR. Reattached trim on both sides with brad nails and filled holes with matching putty.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b> \$17.00	
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b> \$17.00	
	<b>Notes</b>			

### Labor

<b>Line# 2</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	20-66-01-16-000689	Assist Door Handle - Folding - Exterior/Entry Doors/Replace/Structure		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-06-04 13:11:33 :: OUTSIDE HANDLE @ENTRANCE DOOR WON'T LOCK OUTSIDE HANDLE AT ENTRANCE DOOR WONT LOCK IN PLACE Holes in folding handle don't align to put locking pin back in. Enlarged inner holes to allow pin to go all the way thru handle.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b> \$34.00	
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b> \$34.00	
	<b>Notes</b>			

### Labor

<b>Line# 3</b>	<b>Operation Code</b>	<b>Operational Description</b>		
	30-101-24-00-001074	Interior Door Jamb, U-Channel, Casing, Frame - Interior/Interior Doors/Repair/No Tread Code		
	<b>Complaint, Cause, Correction</b>			
	Original Note : bhoffman@americanrvcenter.com, 2024-06-04 13:12:10 :: REAR BUNK DOOR WILL NOT CLOSE READ BUNK DOOR WILL NOT CLOSE Door is hitting at top edge of door frame. Removed door from opening. Lowered hinge mounting holes 1/8 inch. Remounted door to doorframe. Checked operation of door. Door now closes and latches.			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$51.00	
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$51.00	
	<b>Notes</b>			
	AUTHORIZED AS REQUESTED			

<b>Submitted</b>	Labor Amt	\$102.00
	Parts & Freight	\$0.00
	Total	\$102.00

<b>Approved</b>	Labor Amt	\$102.00
	Parts & Freight	\$0.00
	Total	\$102.00

---

<b>DEALER</b>	<b>DATE</b>
<b>SIGNATURE</b>	

I certify that I have performed these repairs consistent with Forest River Policies.

---

<b>CUSTOMER</b>	<b>DATE</b>
<b>SIGNATURE</b>	

All repairs described have been inspected and are satisfactory.