

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1980751
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXPB2SS047892
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT251RBK
		DEALER RO #	74101
		CLAIM START DATE	07/10/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor
Line# 1

Operation Code
70-147-24-00-001769

Operational Description
TV Coax Cable - Appliances/Television/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2024-07-10 15:16:25 :: ANTENNA IS NOT GETTING CHANNELS TIGHTENED ALL COAX FITTNGS. REMOVED ANTENNA TO CHECK CONNCTION. NOTICED THAT THE PURPLE WIRE IS COMING FROM THE ANTENNA. THE BOOTER HAD THE BLACK WIRE INSTALLED ON THE ANTENNA SIDE OF THE BOSTER. SWAPPED PURPLE AND BLACK COAX. RAN CHANNEL SCAN. ALL COAX INLETS ARE GETTING CHANNELS.

Model#	Dlr Sub Hrs	0.70	Sub Labor Amt \$119.00
Serial#	Appr Hrs	0.70	Appr Labor Amt \$119.00

Notes

Labor
Line# 2

Operation Code
20-43-19-00-004330

Operational Description
Spot Seal Exterior (Dealer) - Exterior/Exterior Miscellaneous/Reseal/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2024-07-10 15:17:12 :: ROOF NEEDS SEALED SEALED ROOF AS NEEDED WITH DICOR.

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt \$68.00
Serial#	Appr Hrs	0.40	Appr Labor Amt \$68.00

Notes

Labor
Line# 3

Operation Code
20-66-02-17-000672

Operational Description
Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2024-07-10 15:18:01 :: ENTRY DOOR NEEDS ADJUSTED Repositioned latch for entry door.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00

Notes

Labor
Line# 4

Operation Code
20-57-24-00-000601

Operational Description
Sidewall - Exterior/Exterior Fiberglass Walls/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2024-07-10 15:18:52 :: RED MARK ON SIDEWALL OUTSIDE Removed mark with mineral spirits and a rag.

Model#	Dlr Sub Hrs	0.15	Sub Labor Amt	\$25.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

**Labor
Line# 5**

Operation Code	Operational Description
30-101-02-00-001077	Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code
Complaint, Cause, Correction	
Original Note : bhoffman@americanrvcenter.com, 2024-07-10 15:19:29 :: BATHROOM DOOR WONT LATCH Repositioned latch.	

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Submitted	Labor Amt	\$263.50	Approved	Labor Amt	\$255.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$263.50		Total	\$255.00

DEALER **DATE**
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE
 All repairs described have been inspected and are satisfactory.