



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74101



CUSTOMER WORK ORDER

WO #: 74101

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0715 CHECK WORK

Stock #: 11418
Stock Desc: 2025 TT FOREST RIVER
APEX 251RBK
Chassis #: 5ZT2CXPB2SS047892
Serial #: 5ZT2CXPB2SS047892
Mileage: 0
Licence:

Invoice #:
Date In: 01 JUL 24
Promised:
Date Sched:
Completed: 11 JUL 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: checked tire pressure,torqued lugs, running lights,brakes,all interior lights,all appliances, plumbing and electrical system, holding tanks,filled l.p. ran l.p. drop test, checked doors,drawers,documented model and serial numbers,installed stickers and battery box.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ANTENNA IS NOT GETTING CHANNELS

CAUSE: TIGHTENED ALL COAX FITTNGS. REMOVED ANTENNA TO CHECK CONNCTION. NOTICED THAT THE PURPLE WIRE IS COMING FROM THE ANTENNA. THE BOOTER HAD THE BLACK WIRE INSTALLED ON THE ANTENNA SIDE OF THE BOSTER. SWAPPED PURPLE AND BLACK COAX. RAN CHANNEL SCAN. ALL COAX INLETS ARE GETTING CHANNELS.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	119.00

Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 119.00

Job #2 - Warranty

COMPLAINT: ROOF NEEDS SEALED

CAUSE: SEALED ROOF AS NEEDED WITH DICOR.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	68.00

Subtotal for Job #2: 68.00

Job #3 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Repositioned latch for entry door.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00

Subtotal for Job #3: 34.00

Job #4 - Warranty

COMPLAINT: RED MARK ON SIDEWALL OUTSIDE

CAUSE: Removed mark with mineral spirits and a rag.

CORRECTION: .

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00

Subtotal for Job #4: 17.00

Job #5 - Internal

COMPLAINT: OUTSIDE FRIDGE DOOR IS DENTED AND SCRATCHED

CAUSE: Scratch was on plastic. Removed plastic and door still has a dent.

CORRECTION: .checked with b.h. dent is too small to try to get covered.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: BATHROOM DOOR WONT LATCH

CAUSE: Repositioned latch.

CORRECTION: .

Labor



Customer #: 1000
BASDEN'S AMERICAN RV,



Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00

Subtotal for Job #6: 17.00

W/O: 74101

Parts Total: 0.00
 Labour Total: 255.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 255.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 11 Jul 2024



Customer #: 1000
 BASDEN'S AMERICAN RV,

