



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 74172
Promised Date:
24 JUL 24



Customer #: 52264
KRUSE, TYLER L.



CUSTOMER WORK ORDER

WO #: 74172 (Appointment Date: 09 JUL 2024 - Time: 09:00am)

Customer: 52264 - KRUSE, TYLER L. -

Tag: BJ - T-STAT ORDERED 7-12-24

Author: BJW

Location: 0723 BH TO CLOSE

Stock #:

Stock Desc: 2024 TT COACHMEN

CATALINA SUMMIT SERIES 261BHS

Chassis #: 5ZT2CARB0RU042456

Serial #: 5ZT2CARB0RU042456

Mileage: 0

Licence:

Invoice #: 407379

Date In: 09 JUL 24

Promised: 31 JUL 24

Date Sched:

Completed: 24 JUL 24

Warr. Date: 30 JAN 24

Job #1 - Warranty

COMPLAINT: AC IS NOT COOLING AND THEROSTAT CAME OFF THE WALL.
CUSTOMER NEEDS UNIT BACK BY 0716 FOR A PLANNED WEEKEND TRIP.

CAUSE: Ac not cooling

CORRECTION: Plugged in the shore power cord then went to the thermostat and set the ac to 67 degrees. It is 80 degrees outside. Put a thermometer in the intake and output on the ac. Temp was only at a few degrees difference. Took pictures of the ac. Inspected the thermostat and it was not holding to the wall mount. Received the new ge ac. Removed the ceiling cover to the ac to unbolt and disconnect the power source. Went to the roof and removed the bad ac. Unboxed the new ac then took it up on the roof. Went back inside and bolted the new ac in place. Plugged in the power, went to the thermostat and turned the ac and let it run for 20 minutes. Ac cool till the thermostat was satisfied.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	100.30
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	69.70
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	170.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	14.85	14.85

Subtotal for Job #1: 354.85

Job #FALLROOF - External

COMPLAINT: COMPLETE ROOF INSPECTION - ADVISE CUSTOMER OF ANY ISSUES. (SEALANT NOT INCLUDED).

CUSTOMER ADVISES THAT THERE ARE BUBBLES FORMING ON THE TOPS.

CAUSE: Bubbles filled

CORRECTION: Inspected the roof and found the spots that had bubbles. Cleaned and applied dicor sealer as needed. Found no other sealer needing a touch-up.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C



Subtotal for Job #FALLROOF: 0.00

Job #2 - Warranty
THERMOSTAT IS OFF WALL

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	51.00

Parts				
Part #	Description	Qty	Price	Total
F100238139	THERMOSTAT, GE BLK- A/C HEAT/COOL,	1.00	36.05	36.05

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-T-STAT	1.00	18.26	18.26

Subtotal for Job #2: 105.31

Parts Total: 36.05
Labour Total: 391.00
Sublet Total: 0.00
Extras Total: 33.11
WORK ORDER TOTAL: 460.16

Thank you for being a valued customer. We appreciate your business.
All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 24 Jul 2024

W/O: 74172
Promised Date: 31 JUL 24



Customer #: 52264
KRUSE, TYLER L.

