

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2042461
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB29SK091575
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	094 / 094A
OWNER INFORMATION		ITEM #	CKT26DBH-94
		DEALER RO #	74532
		CLAIM START DATE	08/30/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-103-24-00-001136	Interior Step - Interior/Flooring/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:15:46 :: STEPS HITTING DOOR FRAME Bracket was hitting door frame. Moved Bracket to clear.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
Notes				

Labor

Line# 2	Operation Code	Operational Description		
	30-95-24-00-000948	Dinette Table Top - Booth - Interior/Dinette/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:16:29 :: SCRATCHES ON DINETTE TABLE			
	Cleaned with mineral spirits.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
	Notes			
	repaired			

Labor

Line# 3	Operation Code	Operational Description		
	20-66-24-00-000658	Entry Door - Exterior/Entry Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:17:30 :: ENTRY DOOR NEEDS ADJUSTED The latch for the entry door was crooked. Straightened latch and tightened screws.			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$17.00
	Serial#	Appr Hrs	0.10	Appr Labor Amt \$17.00
	Notes			
	repaired			

Labor

Line# 4	Operation Code	Operational Description		
	40-196-12-00-001306	LED Light - Electrical/12 Volt Interior/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:18:19 :: LIGHT COVER FELL OFF IN KITCHEN			
	Secured light cover.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor

Line# 5

Operation Code
30-103-24-00-001125

Operational Description
Linoleum - Interior/Flooring/Repair/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:19:05 :: GLUE ON FLOOR IN KITCHEN
Removed glue with mineral spirits and a rag

Model#
Serial#

Dlr Sub Hrs
Appr Hrs

0.15
0.15

Sub Labor Amt \$25.50
Appr Labor Amt \$25.50

Notes
cleaned off glue

Labor

Line# 6

Operation Code
20-66-02-00-000687

Operational Description
Screen Door Latch - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2024-08-30 12:19:39 :: REAR SCREEN DOOR HITTING LATCH
Moved latch over with hammer

Model#
Serial#

Dlr Sub Hrs
Appr Hrs

0.05
0.05

Sub Labor Amt \$8.50
Appr Labor Amt \$8.50

Notes

Submitted	Labor Amt	\$119.00	Approved	Labor Amt	\$119.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$119.00		Total	\$119.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.