

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
BASDEN RV CENTER INC		<b>CLAIM</b>	2045427
DBA AMERICAN RV CENTER		<b>CLAIM ORIGIN</b>	WEB
600 E BASELINE ROAD		<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725		<b>VIN</b>	4X4TCKE23SX164874
USA		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$170.00	<b>SITE/WAREHOUSE</b>	017 / 017A
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	ACKT29QB
		<b>DEALER RO #</b>	74655
		<b>CLAIM START DATE</b>	09/03/2024
		<b>CLAIM END DATE</b>	01/01/1900

Retail Date of Purchase	WARRANTY EXPIRATION DATE
-------------------------	--------------------------

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	20-66-02-17-000672
<b>Operational Description</b>	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
<b>Complaint, Cause, Correction</b>	Original Note : bhoffman@americanrvcenter.com, 2024-09-03 15:10:20 :: FRONT ENTRY DOOR AND SCREEN DOOR HITTING LATCH FRONT ENTRY DOOR AND SCREEN DOOR HITTING LATCH Adjusted entry door striker plate and screen door latch. Checked operation after adjustment. Door and screen now closing ok.
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20 <b>Sub Labor Amt</b> \$34.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.20 <b>Appr Labor Amt</b> \$34.00
<b>Notes</b>	

### Labor

**Line# 2**

<b>Operation Code</b>	30-101-02-00-001076
<b>Operational Description</b>	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code
<b>Complaint, Cause, Correction</b>	Original Note : bhoffman@americanrvcenter.com, 2024-09-03 15:11:16 :: BATHROOM DOOR LEADING TO BEDROOM IS HITTING THE FRAME BATHROOM DOOR LEADING TO BEDROOM IS HITTING THE FRAME Hinge screws at top of door are loose. Tightened hinge mounting screws. Dor now closes without hitting frame.
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20 <b>Sub Labor Amt</b> \$34.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.20 <b>Appr Labor Amt</b> \$34.00
<b>Notes</b>	

### Labor

**Line# 3**

<b>Operation Code</b>	20-66-02-17-000672
<b>Operational Description</b>	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
<b>Complaint, Cause, Correction</b>	Original Note : bhoffman@americanrvcenter.com, 2024-09-03 15:14:21 :: REAR DOOR AND SCREEN DOOR HITTING FRAME REAR DOOR AND SCREEN DOOR HITTING FRAME Adjusted screen door latch. Drilled new mounting holes for entrance door striker plate. Mounted striker plate in new holes. Checked operation of screen door and entrance door. Both now closing ok.
<b>Model#</b>	<b>Dlr Sub Hrs</b> 0.20 <b>Sub Labor Amt</b> \$34.00
<b>Serial#</b>	<b>Appr Hrs</b> 0.20 <b>Appr Labor Amt</b> \$34.00
<b>Notes</b>	

<b>Submitted</b>	Labor Amt	\$102.00	<b>Approved</b>	Labor Amt	\$102.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$102.00		Total	\$102.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

All repairs described have been inspected and are satisfactory.