



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75684
Promised Date: 31 DEC 24



CUSTOMER WORK ORDER

WO #: 75684
Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0120 WAITING FOR BILLING
FROM FIBER NEW

Stock #: 11516
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 261BHS
Chassis #: 5ZT2CARB8SU044963
Serial #: 5ZT2CARB8SU044963
Mileage: 0
Licence:

Invoice #:
Date In: 11 DEC 24
Promised: 31 DEC 24
Date Sched:
Completed: 17 JAN 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*75785 on 03 JAN 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: CHECKED APPLIANCES ELECTRICAL AND PLUMBING SYSTEM. FILLED L.P. TANKS. RAN
L.P. DROP TEST. FILLED AND DRAINED TANKS. CHECKED DOORS, DRAWERS AND CABINETS.
INSTALLED BATTERY BOX.

CORRECTION: .

Labor		Mechanic	Total
Code	Description	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services		Qty	Price	Total
Code	Description	0.00	N/C	N/C
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES			

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: Transferred to BAS*75785 on 03 JAN 25
Estimate amount was 0.00
WINTERIZE UNIT AND DRAIN HOLDING TANKS.
INCLUDES 2 GALLONS OF ANTI-FREEZE
UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA
DE-WINTERIZATION IS NOT INCLUDED
NUMBER OF GALLONS USED _____

CAUSE: RAN A.F. THROUGH LINES AND FIXTURES. DRAINED ALL TANKS,

CORRECTION: .

Labor		Mechanic	Total
Code	Description	ZMS	N/C
Z990	WINTERIZE UNIT		



Customer #: 1000
BASDEN'S AMERICAN RV,





Other Services		Qty	Price	Total
Code	Description			
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #WINTER:				0.00

Job #1 - Warranty

COMPLAINT: THE BLACK TANK FLUSH INLET IS MISSING A GASKET

CAUSE: GASKET/SCREEN IS MISSING.

CORRECTION: INSTALLED GASKET/SCREEN ON INLET.

Labor			Mechanic	Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	17.00

Parts		Qty	Price	Total
Part #	Description			
10-1211	20183 3-PK 1" HOSE FILTERS	1.00	2.12	2.12
Subtotal for Job #1:				19.12

Job #2 - Warranty

COMPLAINT: THE SEALER ON THE WALL BEHIND THE SLIDE ROOM ON THE OUTSIDE IS NOT SEALING PROPERLY.

CAUSE: THERE IS EXCESS SEALER ON THE WALL BEHIND THE SLIDE ROOM.

CORRECTION: APPLIED MINERAL SPIRITS TO THE WALL AND REMOVED WITH A TOWEL.

Labor			Mechanic	Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	34.00
Subtotal for Job #2:				34.00

Job #3 - Warranty

COMPLAINT: THERE IS A SCRATCH ON THE FLOOR. IT IS IN BETWEEN THE VENT AND THE ENTERTAINMENT CENTER.

CAUSE: FIBER NEW CAME AND FIXED

Labor			Mechanic	Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)			0.00

Sublet			Total
Description			
FIBER NEW			375.00
Subtotal for Job #3:			375.00

Job #4 - Warranty

COMPLAINT: THE BATTEN STRIPS ABOVE THE SLIDE IN THE BEDROOM ARE LOOSE

CAUSE: The batten strips came loose above the slide room and one in the bedroom.

CORRECTION: Pushed batten strips onto the ceiling.

Labor			Mechanic	Total
Code	Description			
Z990	MISC LABOUR CODE (EXTERNAL)		ZMS	34.00





Subtotal for Job #4: 34.00

Job #5 - Warranty

COMPLAINT: THERE ARE SEVERAL HOLES IN THE CABINETS UNDER THE SINK AND THE STOVE THAT NEED TO BE FILLED

CAUSE: Staple holes need filled.

CORRECTION: Filled holes with putty.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	17.00
Subtotal for Job #5:			17.00

Job #6 - Internal

COMPLAINT: THERE ARE SOME STAPLE HOLES AROUND THE PANTRY THAT NEED TO HAVE THE PUTTY CLEANED UP FROM AROUND THEM.

CAUSE: Excess putty around staple holes. Staples need set.

CORRECTION: Set staples. Removed excess putty with mineral spirits.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Subtotal for Job #6:			0.00

Job #7 - Warranty

COMPLAINT: THERE IS GLUE ON THE WALL BEHIND THE DINETTE SEAT

CAUSE: GLUE ON WALL.

CORRECTION: APPLIED MINERAL SPIRITS AND REMOVED GLUE WITH TOWEL.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00
Subtotal for Job #7:			34.00

Job #8 - Warranty

COMPLAINT: THERE IS EXCESS SEALER ON THE OUTSIDE REAR WALL. THIS IS ON THE TOP ROOF TRIM.

CAUSE: THERE IS EXCESS SEALER ON THE ROOF TRIM.

CORRECTION: MOVED A LIFT TO THE UNIT. REMOVED SEALER.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00
Subtotal for Job #8:			34.00

Job #9 - Warranty

COMPLAINT: THE ENTRY DOOR IS HARD TO OPEN

CAUSE: DOOR IS STICKING WHEN OPENING,

CORRECTION: APPLIED LUBRICANT TO DOOR LATCH. MOVED LATCH OVER SLIGHTLY WITH HAMMER.





Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	34.00
Subtotal for Job #9:			34.00

Job #10 - Warranty

COMPLAINT: THE TELEVISION WILL NOT PICK UP CHANNELS

CAUSE: PULLED BOOSTER OFF OF WALL. THE COAX CABLE IS NOT CONNECTED TO THE BOOSTER. USED HOOK TOOLS TO PULL COAX THROUGH THE CUT OUT. HOOKED UP COAX TO BOOSTER AND RAN A CHANNEL SCAN. NO CHANNELS WERE FOUND. THE FITTING ON LINE DOESNT LOOK LIKE ITS MAKING A GOOD CONNECTION. CUT END OFF. INSTALLED A NEW COAX FITTING. RAN A CHANNEL SCAN AND TV IS PICKING UP CHANNELS. INSTALLED BOOSTER TO WALL.

CORRECTION: .

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	102.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Subtotal for Job #10:			102.00

Parts Total:	2.12
Labour Total:	306.00
Sublet Total:	375.00
Extras Total:	0.00
WORK ORDER TOTAL:	683.12

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 17 Jan 2025

Customer Signature : _____

