

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 2163534 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CARB2SN300959 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 300 / 300 ITEM # CAT263BHCKLE-300 DEALER RO # 75741 CLAIM START DATE 01/04/2025 CLAIM END DATE 01/01/1900
Labor rate: \$170.00 OWNER INFORMATION	

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description	
30-101-02-00-001076	Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-01-04 11:16:44 :: THE BATHROOM DOOR IS HITTING THE FRAME. NOTED ON DELIVERY Bathroom door rubbing and not closing Adjusted striker plate, hinges and had to remove plastic door jam and remove caulk from where they put to much and caused it to sweel.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
Notes		

Labor

Line# 2

Operation Code	Operational Description	
10-17-01-00-000314	Cable Only - Frame & Chassis/Specialty, Utility Unit/Replace/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-01-04 11:20:28 :: THE POSSITIVE BATTERY CABLE IS TOO SHORT TO REACH THE BATTERY Positive cables to short Removed undercarriage cover and untangled cable. And reinstalled battery box in closer location of cables and zip tied wires together neatly.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.25	\$42.50
Serial#	Appr Hrs	Appr Labor Amt
	0.25	\$42.50
Notes		
AUTHORIZED AS REQUESTED		

Labor

Line# 3

Operation Code	Operational Description	
20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-01-04 11:23:07 :: THE ENTRY DOOR IS HARD TO CLOSE AND IT FEELS LIKE IT IS IN A BIND Door catching on striker plate and step catch. Adjusted striker plate. Added a spacer to step catch.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$34.00
Notes		

Labor

Line# 4

Operation Code	Operational Description	
70-167-19-00-001999	Water Heater - Appliances/Water Heater (Suburban)/Reseal/No Tread Code	
Complaint, Cause, Correction		
Original Note : bhoffman@americanrvcenter.com, 2025-01-04 11:24:15 :: UNIT IS NOT SEALED ALL THE WAY AROUND THE WATER HEATER Not sealed around Hot Water Heater Removed loose caulk and recaulked.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$34.00

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.