

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2192736
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEPB2SW030689
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET247SE-320
		DEALER RO #	75867
		CLAIM START DATE	02/05/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 30-102-15-00-003365	Operational Description Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code	
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:50:43 :: STAIN ON CEILING NEXT TO SPEAKER Pinkish spot on ceiling by speaker... Attempted to clean it but wouldn't remove so I used white paint marker to cover it.		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes touch up		

Labor

Line# 2	Operation Code 30-102-15-00-003365	Operational Description Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code	
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:51:25 :: PANEL UNDER BED IS LOOSE Loose panel under bed area... Stapled panel into place.		
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt \$17.00
	Notes		

Labor

Line# 3	Operation Code 60-141-19-00-001596	Operational Description Tub Surround - Plumbing/Shower, Tub Surround/Reseal/No Tread Code	
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:52:38 :: THE SHOWER LINER IS NOT COMPLETELY SEALED ON ALL SIDES Shower liner not sealed... Used white silicone to seal right side of shower liner. Due to the liners flex between the mount screws creating a bulge i had to apply pressure while sealing and take down to pull liner closer to wall so silicone could seal.		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$34.00
	Notes		

Labor

Line# 4	Operation Code 30-102-01-00-001097	Operational Description Seam Tape, per 8 ft. Strip - Interior/Panels, Ceilings, & Interior Moldings/Replace/ No Tread Code
	Complaint, Cause, Correction	

Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:53:19 :: THE SEAM TAPE UNDER THE EMERGENCY EXIT WINDOW IN THE BEDROOM IS FLAWED Loose/Rippled seam tape.. Applied adhesive and stretched out to remove ripples and make tightened.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor

Line# 5	Operation Code 30-102-15-00-003365	Operational Description Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:53:59 :: THERE IS A WATER STAIN ON THE CEILING ABOVE THE EMERGENCY EXIT IN THE BEDROOM Stain on wall by ceiling in bedroom. Attempted to clean water mark but wouldn't remove so I covered stain with white paint marker lightly. Applied all 2nd layer. Checked in roof and found no poor sealed areas.		

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$17.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes				

Labor

Line# 6	Operation Code 30-100-01-00-001039	Operational Description Cabinet Door Catch - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:54:41 :: THE LATCH ON THE DRAWER NEAR THE BED IN THE BEDROOM DID NOT HAVE BOTH SIDES OF THE LATH ATTACHED PROPERLY FROM MANUFACTURING Drawer next to bed didn't have locking latch installed properly... Installed the locking mechanism with 2 screws.		

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$51.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$17.00
Notes install cabinet catch with 2 screws = 0.10; repair code 30-100-01-00-001039				

Labor

Line# 7	Operation Code 30-102-12-00-002691	Operational Description Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-02-05 15:57:08 :: THE CABINET NEXT TO THE COUCH IS CRACKED AND FLAWED Cracked piece of trim and discolor on wall... Doctored the broken area and matched color of wax puddy to cover.		

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$34.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$34.00
Notes				

Submitted	Labor Amt	\$204.00	Approved	Labor Amt	\$170.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$204.00		Total	\$170.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.