



Warranty Authorization Form

Date: 8/1/2025

General Information

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Ph. (812) 867-5200
cbruce@americanrvcenter.com

Pre-Auth #: 97289

Series: Avenue

Notes: 6/26 Dave H: Dealer: Need vender tag info attached for job 1, as per flat rate code you used. Job 2, what cause this damage?

Status: Approved with Modifications

Unit: 7M5FA3323SA009712

Model: 2025AVE29RL

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 16078 ROOF VENT - LIFT MOTOR - REPLACE - MAXXAIR
(MODEL AND SERIAL NUMBER OF THE UNIT IS REQUIRED)(RVP auth required)

Fault Code: VENDOR

Serial #: Model #:

Notes: 6/30/25: Danielle -- Sent to the vendor please allow 48 hours for vendor response (Business days) 7/1/25: Danielle -- approved a replacement lift motor (10-20270) and scrap the old one

Problem: VENT LID MOTOR LOCKED UP

Time Requested: 1

Cause: LID WILL NOT COME UP AND WONT MOVE

Time Allowed: .5

Remedy: NEED TO REMOVE AND REPLACE IT

Sublet Repairs: 0.00

Part Return Req: Yes

Status: Approved with Modifications

Operation Line 2

Flat Rate Code: 12069A SLIDEOUT - FLOOR - REPAIR

Fault Code: CHIPPED

Serial #:

Model #:

Notes:

Problem: THERE IS A GOUGE IN THE BOTTOM OF THE SLIDE ROOM FLOOR

Time Requested: .3

Cause: Gouged slide room floor on the outside.

Time Allowed: .3

Remedy: Applied tape around the gouged area. Applied wood putty and let dry. Painted with black paint and removed tape.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved