



Warranty Authorization Form

Date: 9/27/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 101515 Unit: 7M5TD3320TC307179
Series: Delta Model: 2026DEL292RL
Notes: 8/12: Dayra - see pending
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22476 DRAIN - REPAIR

Fault Code: BROKEN

Serial #:

Model #:

Notes:

Problem: THE COLD WATER LOW POINT DRAIN VALVE IS BROKEN

Time Requested: .2

Cause: Broken low point valve

Time Allowed: .2

Remedy: Saw low point valve had broken. Removed old valve and replaced with new

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 20075B WATER PUMP - REPLACE (Photo of model/ serial number)

Fault Code: VENDOR

Serial #:

Model #:

Notes: 8/14: Dayra - after review this is our newest pump - Wesco VCB no Vendor PA needed. 8-12 BEN -- PHOTOS ADDED THANK YOU 8/12: Dayra - this doesn't look like a product installed by ARV - please advise where this is - and close up photo of the tag

Problem: check the pump not working right and making lights flicker and WH not working

Time Requested: .75

Cause: faulty pump might be installed upside down

Time Allowed: .5

Remedy: when running the hot water only the pump is pulsing and will not let the WH run correctly. when the pump was pulsing the lights on the inside were flickering we got a surflow pump and installed it where the other pump was and primed the system and didnt have any issues and the WH worked fine

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications

Operation Line 3

Flat Rate Code: 12031A ENTRANCE DOOR - REPLACE (Photos required)(Vendor auth required)

Fault Code: MARRED / SCRATCHED

Serial #:

Model #:

Notes:

Problem: SCATCH ON BOTTOM LEFT CORNER OF ENTRY DOOR

Time Requested: 2.1

Cause: Scratch on entry door glass

Time Allowed: 1

Remedy: During pdi of the unit I noticed scratches on, the glass of entry door. Pictures taken and parts request put in

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved with Modifications