



# Warranty Authorization Form

Date: 8/27/2025

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd  
Evansville, IN 47725  
Ph. (812) 867-5200  
cbruce@americanrvcenter.com

### General Information

Pre-Auth #: 103100                      Unit: 7M5TD3322SC305724  
Series: Delta                              Model: 2025DEL294RK  
Notes:  
Status: Approved with Modifications

### Dealer Information

American RV  
(812) 867-5200  
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV  
600 E Baseline Rd  
Evansville, IN 47725

Requestor: Ben Hoffman  
Return Fax #:  
Email: bhoffman@americanrvcenter.com

### Operation Line 1

*Flat Rate Code:* 20012A FRESH WATER LINE - REPAIR (photos required)    *Fault Code:* PART MISSING

*Serial #:*                                      *Model #:*                                      *Notes:*

*Problem:* CUSTOMER ADVISES THAT THE TANK FLUSH INLET PORT IS LEAKING WHEN UNDER PRESSURE.

*Time Requested:* .3

*Cause:* Tank flush valve leaking

*Time Allowed:* .1

*Remedy:* After tanking out the customers 90 degrees hose adapter i found that there wasn't a rubber washer in it. I put a rubber washer in it and all good now no leaks

*Sublet Repairs:* 0.00

*Part Return Req:* No

*Status:* Approved with Modifications

### Operation Line 2

*Flat Rate Code:* 14085 TRIM - INTERIOR - REPAIR                      *Fault Code:* MISALIGNED

*Serial #:*                                      *Model #:*                                      *Notes:*

*Problem:* THERE IS A PIECE OF WOOD THAT IS MISALIGNED UNDER THE CABINET IN THE DOOR SIDE REAR CORNER OF THE COACH. GET BJ IF YOU HAVE QUESTIONS WHERE THIS IS LOCATED.

*Time Requested:* .1

*Cause:* A piece of wood misaligned

*Time Allowed:* .1

*Remedy:* The piece of annoying trim under the cabinet come loose. I shot some stapels in the piece and it looks better now

*Sublet Repairs:* 0.00

*Part Return Req:* No

*Status:* Approved