

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 78112  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 53413 - CHRISTOPHER FOSTER  
Address: 4608 SWEETSER AVE EVANSVILLE, IN

47714

Phone: (812) 773-7545

Stock Number: 11673 - 2026 CATALINA 343BHTSLE 5ZT2CAZB9TX036189

VIN: 5ZT2CAZB9TX036189 HIN: SER#: 5ZT2CAZB9TX036189

Mileage: 0 Work Order Comp: 14 JAN 26

Auth. No: Dealer #:

Warr. Date: 23 OCT 25 Work Order Date: 22 OCT 25 Inv #: 425852

\*\*\*\*\*

WO #	Job #	Description	JOB INFORMATION
78112	5	LIGHT OVER THE KITCHEN COUNTER ISN'T WORKING Light don't work Took light off and it flickerd but won't stay on. So i replaced it and it works properly now	
78112	6	SCRATCH ON THE OUTSIDE OF NUMBER 3 SLIDE WINDOW FRAME Scratch on 3rd slideroom bottom window Inspection of exterior found a scratch on 2 spots on the window frame. Put in a parst request for a new window.	
78112	7	ON THE METAL BEHIND NUMER 1 SLIDE ON THE OFF DOOR SIDE Dent in exterior metal Found dent in metal on exterior inspection. Put in a parts request	
78112	8	CITY WATER INLET IS LEAKING City fill port leaking when the water pump was on Inspection of the cty port it was dripping a little when pressurized. Tryed to see if debris was making it do that but i ended up changing it for a new one. Took leaky one off put budle tape on new one and tightened the water line then installed it and then sealed the outside with silicone and tested it no leaks. Good to go	
78112	1	OUTDOOR KITCHEN CEILLING IS SAGGING DOWN Outdoor ceiling was not secure	

Claim : 78112

\*\*\*\*\*  
 WO # Job # Description JOB INFORMATION  
 \*\*\*\*\*

After inspection of the outside kitchen are i found that the ceiling wasn't secure in the front. So i shot some stapels along the front and filled with putty. Good to go now

78112 3 CLOSET IN MASTER BEDRRM HAS COME OUT OF IT'S TRACKS  
 Closet track guide out of track  
 Upon exterior inspection found that clost door was not moving properly. Found that on of the plastic guides was out of the track so i put it back in and door works properly

78112 4 2 WINDOW SEALS WERE TUCKED IN CAUSING VOID AROUND WINDOW  
 Window seal had a void in it  
 On my inspection of the exterior i found the the window seal wasn't installed correctly. So i got the seal installed correctly and is good to go now

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
F100330465	5	LIGHT, 4.5" MUSHROOM CEILING LIGH		1.00	2.30	2.30
C01275870	6	WINDOW, PUSH EGRESS 21-5/8 x 29-5		1.00	82.59	82.59
F100359506	6	SILICONE, NEUTRAL CURE SILICONE 1		1.00	13.66	13.66
F100708501	7	METAL, .024 X 12 X 156 1MDM SL ME		1.00	36.62	36.62
GC66100	7	Geocel 2300 Construction Tripolym		1.00	13.35	13.35
681205	8	62145 PW PLASTIC MPT CITY WATER F		1.00	15.48	15.48

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.60	185.00	111.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		2.00	185.00	370.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		2.00	185.00	370.00
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00

\*\*\*\*\*

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	5	UPS-LIGHT		1.00	15.81	15.81

