

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2533071
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKFC7TY039024
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	095 / 095A
Labor rate:	\$185.00	ITEM #	CKT17SC-95
OWNER INFORMATION		DEALER RO #	78713
		CLAIM START DATE	12/19/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-100-02-00-003062	Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-19 14:19:03 :: BATHROOM CABINET DOORS RUBS HARD TO CLOSE Cabinet doors are even and rubs when shut. Adjusted the hinges on on side.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50	
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	60-138-01-00-001537	Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-19 14:19:31 :: HOSE BROKEN UNDER SINK Vacuum breaker hose connection is broken Removed hose and vacuum breaker. Spoke with Ben, was told to replace them. Spoke with Chandler in parts and he retrieved both for me. Installed them back into position.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50	
Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50	
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	30-101-01-00-001092	Sliding, Pocket Door Mirror Trim - Interior/Interior Doors/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-19 14:21:32 :: BED TO BATH LEFT DOOR TRIM TOP Both sides of Door frame are damaged Inspected and measured damaged plastic frame between bedroom and bathroom. 3in wide, 1/2in lip on both sides, 155in in length (77 1/2in x 2 pieces).			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50	
Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50	
	Notes			

Labor

Line# 4	Operation Code	Operational Description		
	10-7-01-00-000147	Grit Tape - Frame & Chassis/Manual Entry Step/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-12-19 14:24:46 :: TAPE ON THE ENTRY STEPS Grip tape on steps are damaged Measured 2in x 18in grip tape part requested. Received new grip tape strip from parts. Removed damaged tape from steps and cleaned adhesive and installed new strip.			

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Labor

Line# 5	Operation Code	Operational Description		
	30-102-08-00-002279	Wall Panel - Interior/Panels, Ceilings, & Interior Moldings/Overlay/No Tread Code		
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-12-19 14:25:22 :: CABINET ABOVE KITCHEN SINK WALL DOWN Inside cabinet a false was was just laying and not installed. Measured and attached support boards on panel and installed in cabinet.				
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
Notes				

Submitted	Labor Amt	\$222.00	Approved	Labor Amt	\$222.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$222.00		Total	\$222.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.