

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 78848
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 46875 - CHUBBY CHOW FACTORY LLC
Address: PO BOX 3641 EVANSVILLE, IN

47735

Phone: 812-455-2400

Stock Number: 2601R - 2026 FREELANDER 27QB 1FDWE3FN9SDD30100

VIN: 1FDWE3FN9SDD30100 HIN:

SER#: 1FDWE3FN9SDD30100

Mileage: 5950

Work Order Comp: 17 FEB 26

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 19 JAN 26

Inv #: 426548

WO # Job # Description JOB INFORMATION

78848 1 RECALL 25V486 FR ID 51-1955

Fule line recall

Disconnected Batteries, drive and house, as instructed in Recall procedure but was unnecessary cause Correction Kit has to be ordered 1st... so i Part Requested Kit and reconnected batteries.

Unplugged fuel pump control module. Clamped off both ends of the line. Unplugged the line on bothe ends pulled it throught the frame holder. Rand new line in frame holder and installed both ends to line plugged in module checked for leaks. Good to go.

78848 2 CAP LIGHTS ARE TURNING PURPLE

Located Cap light switch in overhead bed compartment and 2nd switch by Entry door and turned lights on... took pics and part requested new lights.

78848 4 USB PORT AT ENT DOOR IS NOT CHARGING

C type port has no voltage.

Located USB/C type port inside entrance door and tested voltage on both... USB is working properly but the C type has no voltage. Part requested new Port. Received new USB Port from Parts and installed and tested.

78848 3 BLANK TANK BRACKET IS LOOSE

Unmounted Tank Band end.

Jacked up unit at the area of black tank and inspected the loose bracket... it was in a stuck pinned in area and actually has

Claim : 78848

WO #	Job #	Description	JOB INFORMATION
------	-------	-------------	-----------------

another tank support bracket, it looks like they installed the secondary support because the support band has no clearance to be mounted as designed. I was barely able to get unsecured end of bracket band out of pinned position on outside of Bracketed area. Mounted with a Lag Screw and added a 2nd lag thru Band for extra support.

Part No	Job#	Description	PARTS	Qty	Price	Total
F100231286	1	32" FUEL LINE RECALL KIT		1.00	40.95	40.95
F100584060	2	BADGE, KIT BACKLIT LENS RH/LH 2-L		1.00	109.10	109.10
F100130007/FR	4	CHARGER, DUAL USB (2 PORTS) 5V BL		1.00	6.18	6.18

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.40	185.00	74.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.15	185.00	27.75
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	1	UPS-FUEL LINE		1.00	16.26	16.26
FRT	2	UPS-LIGHTS		1.00	16.26	16.26

Parts Total:	156.23
Labour Total:	388.50
Sublet Total:	0.00
Extras Total:	32.52

>>>> Claim Total: 577.25

Customer Signature: _____

Date: _____