



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78866
Promised Date: 28 FEB 26

CUSTOMER WORK ORDER

WO #: 78866

Customer: 46875 - CHUBBY CHOW
FACTORY LLC - 812-455-2400

Tag:
Author: BH
Location: 0210 BH TO CLOSE

Stock #: 2604R
Stock Desc: 2026 C COACHMEN
FREELANDER 27QB
Chassis #: 1FDWE3FNXSDD32339
Serial #: 1FDWE3FNXSDD32339
Mileage: 11336
Licence:

Invoice #: 426381
Date In: 20 JAN 26
Promised: 28 FEB 26
Date Sched:
Completed: 11 FEB 26
Warr. Date:



Job #1 - Warranty

COMPLAINT: RECALL 25V486 FR # 51-1955

CAUSE: Recall

CORRECTION: Parts request submitted for recall after pulling plug and trying to start coach

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	92.50

Parts

Part #	Description	Qty	Price	Total
F100231286	32" FUEL LINE RECALL KIT	1.00	40.95	40.95

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-RECALL KIT	1.00	16.26	16.26

Subtotal for Job #1: 242.21

Job #2 - Warranty

COMPLAINT: BLACK TANK HEATING PAD IS STARTING TO FALL OFF.

CAUSE: Black tank heater.

CORRECTION: Brought unit in. Black tank heater had fallen off. Cleaned up with mineral spirits to get build up off. Once cleaned up used 3m tape prime to stick back with bottle jack to hold wood to keep pad in place. Re,oved wood and jack holding wood in place. Tank heater sticks to tank.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: CAP LIGHTS HAVE TURNED PURPLE

CAUSE: Cap lights

CORRECTION: Cap lights have turned purple when lit parts request submitted

Customer #: 46875
CHUBBY CHOW FACTORY
LLC,





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	12.95
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	35.15
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	25.90

Parts				
Part #	Description	Qty	Price	Total
F100584060	BADGE, KIT BACKLIT LENS RH/LH 2-LIGH	1.00	109.10	109.10

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-CAP LIGHT	1.00	16.26	16.26

Subtotal for Job #3: 199.36

Job #4 - Warranty

COMPLAINT: BEDROOM WALL OPPOSITE SHOWER HAD BOWED AND POPPED LOOSE.

CAUSE: Wall board

CORRECTION: Grent inside and wall board in bedroom was bowing. Removed trim on wall board and pulled staples. Cut excess off of bottom of wallboard once i had pulled the bottom half out. Cut and mesured until board wasnt bowing. Once done stapled back on and looked for and found trim for bottom over board to cover removed board. Cut to length and stapled both trim in place. Made grey wood putty and covered staples

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #4: 37.00

Job #6 - External

GENERATOR RUBBER VIBRATION BUMPERS
 SQUEAK W/ GENRATOR STARTS AND STOPS.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #6: 0.00

Job #7 - External

COMPLAINT: Transferred to BAS*78925 on 30 JAN 26
 Estimate amount was 0.00
 TOUCH UP ROOF SEALANTS AS NEEDED

CAUSE: Roof seal

CORRECTION: Grabbed lift. Went to roof and found small voids. Filled voids with dicor

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #7: 0.00



Job #8 - External

COMPLAINT: Transferred to BAS*78925 on 30 JAN 26
Estimate amount was 0.00
LP PRESSURE TEST

CAUSE: Lp test

CORRECTION: Brought unit in connected to outside port lp line. Starting pressure was 13.5iwc. At 50% run with furnace and range dropped to 12wci. Lock up pressure stops at 13.5 wci. Ran at 8wci for 5mins for leak test. Unit passed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Subtotal for Job #8:			0.00

Job #9 - Internal

COMPLAINT: I DONT THINK THE GREY WATER TANK HTR WAS EVER INSTALLED. BILLED OUT BUT NOT INSTALLED

CAUSE: Grey tank heater

CORRECTION: Brought unit in. Saw grey tank heater was zip tied to knife valve and torn up. Parts request submitted formnew tank heater

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Subtotal for Job #9:			0.00

Parts Total:	150.05
Labour Total:	333.00
Sublet Total:	0.00
Extras Total:	32.52
WORK ORDER TOTAL:	515.57

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 11 Feb 2026

Customer Signature : _____



Customer #: 46875
CHUBBY CHOW FACTORY
LLC,

