



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79158
Promised Date:
no M A D 26

CUSTOMER WORK ORDER

WO #: 79158

Customer: 50939 - ALVEY, GREGORY -
270-993-1229

Tag:

Author: BH

Location: DELIVERY 0309

Stock #: 11530

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 324RLDS

Chassis #: 5ZT2FEXB6SW030243

Serial #: 5ZT2FEXB6SW030243

Mileage: 0

Licence:

Invoice #:

Date In: 03 MAR 26

Promised: 09 MAR 26

Date Sched:

Completed: 19 MAR 26

Warr. Date: 09 MAR 26

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery air pressure correct in all 5 tires. Exterior inspection both awnings work properly. Seal on the outside kitchen area has a rip in it. Roof inspection looks good. Interior inspection looks good went back over things everything looks good. Replaced the water heater door. The one from factory had rust on it

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	DP24 GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
7278	50F TO 15M ADAPTER	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize unit

CORRECTION: Turned valve to winterize and pumped winterize solution through the pump to bathroom faucet hot and cold until solution was there then repeated for toilet and bathroom shower and kitchen faucet and outside shower. Then depressed city water inlet. Used 2 gallons of winterize solution and drained the black tank and gray tank and fresh tank

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	JTW	N/C
Z990	WINTERIZE UNIT	JTW	N/C



Customer #: 50939
ALVEY, GREGORY



Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: Hitch work
 New hitchwork installation

CORRECTION: Had to move the spare tire back so i could have room for my hitch brakets. Got the hitch brakets installed on the camper and put the rest of the hitch in side compartment. Leveled the camper then checked the ball height and matched the truck. Connected the truck to the camper and adjusted as needed. Tightened all hardware. Connected the 7 way ,safety chains, breakaway cable and coupler.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #1 - Internal

COMPLAINT: REPLACE THE LIVING ROOM SWITCH WITH A DIMMER

CAUSE: Install dimmer switch

CORRECTION: Took old switch out and tested the wires because new switch had 3 wires and old switch had 2 wires. Got it installed and it works properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
72-7034	LED DIMMER SWITCH	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING-SWITCH	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #COVER-L - Internal

COMPLAINT: INSTALL (2) LARGE SLIDE COVERS 138" TO 192"

CAUSE: Install slideroom toppers

CORRECTION: Door side slideroom topper we had to take awning arms loose to be able to get brackets





on. Had to cut topper bars off so they didn't hit slideroom awning. Off door side slideroom topper we had to mount the gutter rail that we put budle tape on backside then secured it to the side of the unit and installed slide topper. Ran both sliderooms out and toppers work properly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
V000163298	12.5FT SLIDER-150INWHITE-W HRDWRE-WH	1.00	N/C	N/C
V000163301	14FT SLIDER-14FT WHITE-W HRDWRE-WHIT	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #COVER-L: 0.00

Job #COVER-S - Internal

COMPLAINT: INSTALL SMALL SLIDE COVER 66" TO 96"

CAUSE: Install small slide topper

CORRECTION: We got the brackets mounted and the gutter rail with budle tape on it. And got ready to install topper fabric and noticed a hole in the fabric when we took it from the bag. Put a request in for a new fabric. We got the new topper in and put on and it works properly. And put all the parts back in tube with defective topper and gave it to Chandler

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
12766	6.5FT SLIDER-78IN WHITE-W HRDWRE-WHI	1.00	N/C	N/C

Subtotal for Job #COVER-S: 0.00

Job #2 - Warranty

COMPLAINT: REPLACE TORN GASKET AROUND OUTDOOR KITCHEN

CAUSE: Outside kitchen door gasket ripped

CORRECTION: Took off old gasket cleaned area. And installed the new gasket. Door shuts properly. Good to go

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	58.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
299894	.5" RIBBED DOOR SEAL	16.00	0.57	9.12

Subtotal for Job #2: 67.62

Job #3 - Warranty

COMPLAINT: THE LP REGULATOR IS ADJUSTED AS FAR AS IT WILL GO, AND IT IS STILL NOT IN FACTORY SPECIFICATIONS.





CAUSE: Regulator adjustment bottomed out at 9.9 WC with 50% load

CORRECTION: Removed and replaced regulator with teflon tape on all non-flared fittings. Bubble tested with no leaks present

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50

Parts				
Part #	Description	Qty	Price	Total
06-0443	MEGR-253P LP REGULATOR 2-STAGE	1.00	76.87	76.87

Subtotal for Job #3: 169.37

Job #4 - Warranty

COMPLAINT: WATER HEATER DOOR IS RUSTED

CAUSE: Water heater door

CORRECTION: Water heater door had rust on it in several spots that i removed the whole door and replaced it with a new one. Good to go

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts				
Part #	Description	Qty	Price	Total
07-7912	6285AEB BLK DEMAND WH DOOR - SUBURBA	1.00	60.78	60.78

Subtotal for Job #4: 116.28

Job #WALK - Internal

COMPLAINT: WALK THRU

CAUSE: Walk through with customer.

CORRECTION: Showed the customer all appliances and functions of the unit. Set up tpms. Pulled unit around the front.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #WALK: 0.00

Parts Total: 146.77
 Labour Total: 206.50
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 353.27

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : _____

Date: 19 Mar 2026

W/O: 79158
Promised Date: 09 MAR 26



Customer #: 50939
ALVEY, GREGORY



Customer Work Order

