

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2616332
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB3SN301554
USA		CHASSIS VIN	

Labor rate: \$195.00

OWNER INFORMATION

JOSHUA BURRIS
288 MALLARD CIRCLE
Chandler, IN 47610
USA

MILEAGE	0
SITE/WAREHOUSE	300 / 300
ITEM #	CAT263BHCKLE-300
DEALER RO #	79224
CLAIM START DATE	03/20/2026
CLAIM END DATE	01/01/1900

Retail Date of Purchase 07/19/2025

WARRANTY EXPIRATION DATE 07/19/2026

Claim Line Details

Labor

Line# 1	Operation Code 30-96-24-00-000969 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-20 15:58:06 :: TABLE HAS FALLEN OF MOUNTING POLE Table mount. Brought unit in went inside and saw table had pulled out of mount. Placed feet in position and rotated to not go in same screw holds that had been stripped out. Shot screws in place and secured feet. Put table back together.	Operational Description Folding Table Leg, each - Interior/Folding Leg/Repair/No Tread Code
Model#	Dlr Sub Hrs 0.30	Sub Labor Amt \$58.50
Serial#	Appr Hrs 0.30	Appr Labor Amt \$58.50
Notes	AUTHORIZED AS REQUESTED	

Labor

Line# 2	Operation Code 40-196-01-11-001274 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-20 16:04:33 :: LIGHT IN BATHROOM FLICKERS Light in bathroom Went inside unit and turned on bathroom light. Waited on light and light started flickering while on. Parts request submitted for new light. Recieved new light. Remoced screws from light. Remoced quick connects and plqce new light wires in place. Put wires away and secured light to ceiling with screws. Placed cover over light and checked button. Light works and does not flicker	Operational Description Single Pancake Light - Electrical/12 Volt Interior/Replace/Electrical
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$39.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$39.00
Notes		

Labor

Line# 3	Operation Code 20-62-01-11-000651 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2026-03-20 16:05:02 :: RECEPTACLE COVERS ARE ALL CRACKING IN TO PIECES BY STOVE Switch broken Went inside unit saw switch by range had been broken. Removed screws from wall. Removed wires from switch and replace with new switch. Placed wires in and mounted to wall	Operational Description Powered Roof Vent Switch - Exterior/Power Roof Vent (Elixir & Hengs)/Replace/Electrical
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$19.50
Serial#	Appr Hrs 0.10	Appr Labor Amt \$19.50
Notes		

Labor
Line# 4

Operation Code
30-102-24-00-001117

Operational Description
Trim Molding, each - Interior/Panels, Ceilings, & Interior Moldings/Repair/No
Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2026-03-20 16:08:13 :: TRIM PIECE ON LEFT OF BATHROOM
SINK IS CRACKED AT BOTTOM OF THE WALL Wood separating Went to bathroom and saw wood trim had
started to separate from stables making a gap. Used mallet and light taped wood unitl it closed gap and went
back intonplace.

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.50
Notes				

Submitted	Labor Amt	\$136.50	Approved	Labor Amt	\$136.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$136.50		Total	\$136.50

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.