



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 79224



CUSTOMER WORK ORDER

WO #: 79224 (Appointment Date: 10 MAR 2026 - Time: 04:30pm)

Customer: 55943 - BURRIS, JOSHUA -
812-706-8818

Tag:

Author: GA

Location: 0323 BH TO CLOSE

Stock #:

Stock Desc: 2025 TT COACHMEN

CATALINA 263BHCKLE

Chassis #: 5ZT2CARB3SN301554

Serial #: 5ZT2CARB3SN301554

Mileage:

Licence:

Invoice #:

Date In: 10 MAR 26

Promised:

Date Sched:

Completed: 23 MAR 26

Warr. Date: 02 JUL 25

Job #1 - External

Transferred to BAS*79318 on 20 MAR 26

Estimate amount was 0.00

CHECK SILICONE AROUND WEATHER STRIP. CUSTOMER SEES GAP. BIG GAP ON DOOR SIDE BY MARKER LIGHT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: TABLE HAS FALLEN OF MOUNTING POLE

CAUSE: Table mount.

CORRECTION: Brought unit in went inside and saw table had pulled out of mount. Placed feet in position and rotated to not go in same screw holds that had been stripped out. Shot screws in place and secured feet. Put table back together.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	29.25
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	29.25

Subtotal for Job #2: 58.50

Job #3 - Internal

COMPLAINT: FRONT AWNING ARM DOESN'T GO ALL THE WAY IN

CAUSE: Awning

CORRECTION: Awning would not go in all the way. Went inside to switch to run awning out and in and noticed switch was reversed. Placed wires in correct position and ran awning in and. Out. Awning runs all the way in.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Customer #: 55943
BURRIS, JOSHUA



Subtotal for Job #3: 0.00

W/O: 79224

Job #4 - Warranty

COMPLAINT: LIGHT IN BATHROOM FLICKERS

CAUSE: Light in bathroom

CORRECTION: Went inside unit and turned on bathroom light. Waited on light and light started flickering while on. Parts request submitted for new light. Recieved new light. Remoced screws from light. Remoced quick connects and plqce new light wires in place. Put wires away and secured light to ceiling with screws. Placed cover over light and checked button. Light works and does not flicker

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	5.85
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	33.15

Parts Part #	Description	Qty	Price	Total
479579	LED - Mushroom Light - Ultra Bright - w/Switch	1.00	2.30	2.30

Subtotal for Job #4: 41.30

Job #5 - Warranty

COMPLAINT: RECEPTACLE COVERS ARE ALL CRACKING IN TO PIECES BY STOVE

CAUSE: Switch broken

CORRECTION: Went inside unit saw switch by range had been broken. Removed screws from wall. Removed wires from switch and replace with new switch. Placed wires in and mounted to wall

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	19.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts Part #	Description	Qty	Price	Total
S269	S269 10A BLACK ROCKER SWITCH W/SILVE	1.00	7.25	7.25

Subtotal for Job #5: 26.75

Job #6 - Warranty

COMPLAINT: TRIM PIECE ON LEFT OF BATHROOM SINK IS CRACKED AT BOTTOM OF THE WALL

CAUSE: Wood separating

CORRECTION: Went to bathroom and saw wood trim had started to separate from stables making a gap. Used mallet and light taped wood unitl it closed gap and went back intonplace.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	19.50

Subtotal for Job #6: 19.50

Job #7 - Internal

COMPLAINT: AUTO LEVELING WOULDN'T COME DOWN ALL THE WAY LAST TRIP OUT

CAUSE: Auto level

CORRECTION: Went to tounge jack and ran auto level. After cycling through auto level leveled correctly.



Customer #: 55943
BURRIS, JOSHUA



Retracted and ran again. Auto level worked again leveling camper. Let customer know if they are on uneven surface to use blocks to help jacks from going out of stroke

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Subtotal for Job #7:			0.00

Job #8 - Internal

COMPLAINT: REAR ENTRY DOESNT STAY LATCHED

CAUSE: Rear entry door

CORRECTION: Went to entry door made sure steps were in correct position. Opened and closed rear entry door multiple times and door latches properly. Let customer know to make sure were steps come over door threshold is flush.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Subtotal for Job #8:			0.00

Job #9 - External

812-706-8818

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #9:				0.00

Job #10 - Internal

COMPLAINT: HEAT PUMP DOESNT WORK

CAUSE: Heat pump in ac

CORRECTION: Went to unit and turned on heat pump. Placed thermometer inside and let run. Went to check and thermometer read around 140 degrees Fahrenheit. Heat pump works.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Subtotal for Job #10:			0.00

Parts Total:	9.55
Labour Total:	136.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	146.05

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Mar 2026

