



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 64239
Promised Date: 31 MAY 21

CUSTOMER WORK ORDER

WO #: 64239 (Appointment Date: 19 MAY 2021 - Time: 07:00am)

Customer: 40368 - FEAGLEY, EMILEE J.
- 812-454-4191

Tag:
Author: BH
Location: 0525 BW GAVE BH APPROVAL SHEET

Stock #: 10719
Stock Desc: 2021 TT KEYSTONE SPRINGDALE 335BH
Chassis #: 4YDT33526M3110133
Serial #: 4YDT33526M3110133
Mileage:
Licence:

Invoice #:
Date In: 19 MAY 21
Promised: 31 MAY 21
Date Sched:
Completed: 25 MAY 21
Warr. Date: 08 MAY 21

Job #1 - Warranty

COMPLAINT: 50AMP PLUG NOT WORKING RIGHT CAN NOT LOCK THE CORD IN

CAUSE: screws were put in crooked and stuck thre into plug area

CORRECTION: replaced plug and tested

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	TEL	N/C

Parts

Part #	Description	Qty	Price	Total
5254	A10-50INBKVP 50A POWER INLET BLACK	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 25 May 2021



Customer #: 40368
FEAGLEY, EMILEE J.



Pre-Authorization

Pre-Authorization number PA02832140 Reference no: 64239 Status: Approved Approved by gurlj
 Servicing Name Address Address Approved by Retail sold on
 Dealer VIN VIN

Approved date 5/25/2021

1194 Basden's American RV Basden's American RV 4YDT33526M3110133 5/8/2021
 600 E Baseline Rd
 Evansville, IN 47725

Nu	Root	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	5104314A	Receptacle - 120V	0.00	0.80	0.50		1	0.20	Complaint:50AMP PLUG ON THE BACK OF THE CAMPER NOT WORKING RIGHT, CAN NOT LOCK THE CORD IN PLACE REALLY STIFF TO INSTALL THE CORD Cause:screws were put in crooked and stuck there into plug area and not letting the cord inlet in Correction:had to replace the plug on the back of the camper because the screws had made the round hole not round anymore KRV - Labor time approved and adjusted in accordance with Keystone RV's flat rate manual

Pre-Authorization number PA02832140 0.50

For paper claims only use one pre-authorization number per warranty claim for
 Staple copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company