



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 64254  
Promised Date: 30 JUN 21

### CUSTOMER WORK ORDER

WO #: 64254

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BJW  
Location: 0622 CHSCK STATUS OF  
AUTHORIZATION

Stock #: 10669  
Stock Desc: 2021 TT RIVERSIDE RV  
INTREPID 281DDB  
Chassis #: 59CCC3827ML003976  
Serial #: 59CCC3827ML003976  
Mileage: 0  
Licence:

Invoice #:  
Date In: 20 MAY 21  
Promised: 30 JUN 21  
Date Sched:  
Completed: 24 JUN 21  
Warr. Date:



Customer #: 1000  
BASDEN'S AMERICAN RV,



#### Job #1 - Warranty

COMPLAINT: THE EMERGENCY EXIT WINDOW ON THE OFF DOOR SIDE OF THE FRONT  
BEDROOM FELL OUT.

CORRECTION: PREBILLED TO GWG FOR WHEN UNIT GETS BACK

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	65.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	65.00

#### Parts

Part #	Description	Qty	Price	Total
HR3022B	3022 WINDOW	1.00	81.11	81.11
HRTRE3022B-01 2	WINDOW TRIM RING	1.00	20.00	20.00

#### Other Services

Code	Description	Qty	Price	Total
FRT	UPS-WINDOW	1.00	21.64	21.64

**Subtotal for Job #1: 252.75**

#### Job #2 - Warranty

COMPLAINT: THE WHITE PLASTIC REFRIDGERATOR ROOF TOP  
VENT FELL OFF.

CAUSE: vent cover on roof came off ,mountig screws to short

CORRECTION: removed sealer from holes on vent lid removed screws ,found longer screws installed lid  
,installed longer screws.sealed screw holes on lid. touched up roof on end of vent

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	26.00

**Subtotal for Job #2: 26.00**

#### Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: PDINTT

CORRECTION: PDINTT





Labor Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GWG	N/C

Parts Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY	1.00	N/C	N/C

Other Services Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

**Job #3 - Warranty**

COMPLAINT: MAIN DOOR IS VERY HARD TO OPEN (REAR DOOR) FROM INSIDE AND OUTSIDE

CAUSE: main entry door hitting striker plate hard to close

CORRECTION: removed screws in striker plate installed longer screws to pull striker plate in deeper so it does mt hit .keep adjusting till door closes properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	26.00

**Subtotal for Job #3: 26.00**

**Job #4 - Warranty**

OUTSIDE FRIDGE IN OUTSIDE KITCHEN IS LOOSE AND NOT FASTENED DOWN

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	26.00

**Subtotal for Job #4: 26.00**

**Job #5 - Warranty**

COMPLAINT: OUTSIDE KITCHEN SLIDE THAT HOLD THE GRILL WILL NOT OPEN ALL THE WAY

CAUSE: OUTSIDE KITCHEN PULLOUT FOR GRIDDLE WILL NOT PULL OUT ALL THE WAY

CORRECTION: REMOVED GRIDDLE AND REMOVED SLIDEING DRAWER (HAD TO REMOVE SCREW FROM GLIDERAIL TO GET DRAWER OUT. FOUN THE OTHER 2 SCREWS HAD PULLED OUT KEEPING THE DRAWER GLIDE FROM PULLING OUT . REMOVED SCREWS GOT LONGER SCREWS AND INSTALLED INTO DRAWER GLIDE ADDED 2 EXTRA SCREWS ON BOTH SIDES . REASSEMBLED DRAWER TESTED OPERATION IT NOW PULLS OUT ALL THE WAY. INSTALLED GRIDDLE ON DRAWER

Labor Code	Description	Mechanic	Total
------------	-------------	----------	-------



Z990 MISC LABOUR CODE (EXTERNAL) GWG 65.00

Subtotal for Job #5: 65.00

**Job #6 - Warranty**

COMPLAINT: BATH ROOM DOOR HARD TO OPEN AND CLOSE

CAUSE: door hitting stricker plate

CORRECTION: removed stricker plate reinstalled drilled new screw holes ,had to counter sink screw holes in stricker plate deeper to keep screws from rubbing door

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	26.00

Subtotal for Job #6: 26.00

**Job #7 - Warranty**

COMPLAINT: THE BED ROOM SLIDING DOOR IS LOOSE AND STUCK IN THE DOOR WAY

CAUSE: BEDROOM DOOR DRAGGING FLOOR

CORRECTION: REMOVED COVER AT TOP OF DOOR TO ACCESS DOOR ROLLERS ,PUT ROLLER IN MOUNT ON TOP OF DOOR ,ADJUSTED DOOR ROLLERS ,AND INSTALLED DOOR GUIDE AT BOTTOM OF DOOR. INSTALLED PANEL ABOVE DOOR

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	65.00

Subtotal for Job #7: 65.00

**Job #8 - Warranty**

COMPLAINT: AC DEVIDER MISSING

CAUSE: TOOK PICS OF MISSING DIVERTER

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	0.00

Subtotal for Job #8: 0.00

**Job #9 - Warranty**

AC DUCT WORK NOT TAPPED AND SHOOTING AIR IN ATTIC

BOARD IS BROKEN ABOVE DUCT

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	65.00

Subtotal for Job #9: 65.00

**Job #10 - Warranty**

COMPLAINT: AC BOLTS MISSING

CAUSE: 2 BOLTS MISSING ON THE A/C

CORRECTION: FOUND MISSING BOLTS IN PACKAGE WITH ALL THE PAPER WORK FROM MANUFACTURE .REOMEVED COVEG ON CELING REMOVED FILTERS AND FOUR MOUNTING SCREWS . INSTALLED THE TWO MISSING AC MOUNTING BOLTS ,INSTALLED COVER FILTERS AND

W/O: 64254  
Promised Date: 30 JUN 21



Customer #: 1000  
BASDENS AMERICAN RV,





SCREWS

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	52.00
<b>Subtotal for Job #10:</b>			<b>52.00</b>

**Job #11 - Warranty**

COMPLAINT: BRAKE AWAY SWITCH HANGING AND BUSTED

CAUSE: brakaway switch busted and hanging off

CORRECTION: removed mounting screw, cut wires installed new switch, mounting screw. wired in new switch, tested operation

Labor Code	Description	Mechanic	Total	
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	26.00	
Parts	Description	Qty	Price	Total
80-00-2060	Trailer Breakaway	1.00	16.63	16.63
<b>Subtotal for Job #11:</b>				<b>42.63</b>

**Job #12 - Warranty**

COMPLAINT: DRAWER NEXT TO BATHROOM DRWAER GGLIDE MISSING BEARINGS

CORRECTION: PREBILLED TO GWG

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	52.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	0.00
<b>Subtotal for Job #12:</b>			<b>52.00</b>

**Job #13 - Warranty**

DRAWRS NEXT TO BATHROOM BOTH ARMS FALLING OFF

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	0.00
<b>Subtotal for Job #13:</b>			<b>0.00</b>

**Job #14 - Warranty**

COMPLAINT: BLIND ON BOTTOM BUNK WILL NOT STAY UP

CAUSE: blind will not stay up

CORRECTION: removed screw in string tensioner for blind tightened up string in eyelet installed eye and installed screw tested blind it stays up now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GWG	39.00
<b>Subtotal for Job #14:</b>			<b>39.00</b>



**Job #15 - Warranty**

SIDEWALL HAS DAMAGE, HAS BEEN POORLEY REPAIRED AT FACTORY

**Subtotal for Job #15: 0.00**

**Job #16 - Warranty**

COMPLAINT: THE GALLEY TANK LEVEL INDICATOR DOES NOT REGISTER A READING.

CAUSE: GALLEY TANK LEVEL INDICATOR DOES NOT READ

CORRECTION: TESTEDCUT UNDER BELLY TO GET ACESS TO TANK AND WIRING. CHASED WIRES CHECKED CONECTIONS,, TESTED DIOD PACK DOES NOT WORKHOOKED A TEST DIOD PACK IN A GLASS OF WATER AND MONITOR PANEL WORKS. INSTALLED A NEW DIOD PACK STILL NOT WORKING CHANGED GROUND WIRE FROM TANK TO WIRING HARNESS IT NOW WORKSBUT UNDERBELLY BACK UP AND TAPED SEAME INSTALLED SCREWS TO HOLD UNDERBELLY UP

<b>Labor</b>				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GWG	130.00
Z990	MISC LABOUR CODE (EXTERNAL)		GWG	130.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
10-1148	REPLACEMENT WIRE HARNESS	1.00	9.97	9.97

**Subtotal for Job #16: 269.97**

**Job #17 - Warranty**

COMPLAINT: WATER LEAK BEHIND WATER HEATER

CAUSE: WATER LINE BEHIND WATER HEATER HAS A CUT IN IT

CORRECTION: WATER LINE BEHIND WATER HEATER IS SPRAYING WATER ,FOUND CUT IN LINE NEAR ELBOW REMOVED CLAMP PULLED WATER LINE OFF FOUND CUT ,TRIMED WATER LINE OFF ,INSTALLED NEW CLAMP AND INSERTED ELBOW TIGHTENED CLAMP .PRESSUREIZED SYSTEM CHECKED FOR LEAKS NO LEAK

<b>Labor</b>				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		GWG	65.00

**Subtotal for Job #17: 65.00**

Parts Total:	127.71
Labour Total:	923.00
Sublet Total:	0.00
Extras Total:	21.64
<b>WORK ORDER TOTAL:</b>	<b>1,072.35</b>

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 24 Jun 2021

W/O: 64254  
Promised Date: 30 JUN 21



Customer #: 1000  
BASDEN'S AMERICAN RV,



**RE: 10669 - 2021 RIVERSIDE RV INTREPID 281DDB Ser#: 59CCC3827ML003976,**

Warranty @Riverside RV <warranty@goriversiderv.com>

Thu 6/24/2021 1:13 PM

To: Ben Hoffman <bhoffman@americanrvcenter.com>

I will go ahead and authorize this one this time, but please note that if the unit is coming back to the factory please do not do any further work, we will repair these items here.

062421-2 – 6.1

Job 1 –1.0

Job 2 – .2

Job 3 – .2

Job 4 –.2

Job 5 – .5

Job 6– .2

Job 7 – .5

Job 8 – repair here

Job 9 – .5

Job 10 – .4

Job 11 – .2

Job 12 – .4

Job 13 – repair here

Job 14 – .3

Job 15 – 2

Job 16 – .5



Thanks and have a good day,

*Connie Wilfong*

Warranty Manager

Riverside RV

1775 E US 20

Lagrange, IN 46761

260-499-4578

Ext. 110

---

**From:** Ben Hoffman <bhoffman@americanrvcenter.com>

**Sent:** Wednesday, June 23, 2021 1:19 PM  
**To:** Warranty @Riverside RV <warranty@goriversiderv.com>  
**Cc:** BJ Wright <bjwright@americanrvcenter.com>  
**Subject:** Re: 10669 - 2021 RIVERSIDE RV INTREPID 281DDB Ser#: 59CCC3827ML003976,

CONNIE, I UNDERSTAND THAT YOU DO NOT WORK ON THESE UNITS. WITH THAT BEING SAID IF QUALITY CONTROL WAS DONE UP THERE, WE WOULD NOT HAVE THIS MANY PROBLEMS. AS WE GOT INTO THE INSPECTION, WE FOUND THE A/C HOLE WAS TOO LARGE AND INSTALLED INCORRECTLY AND DAMAGED, AND SCREWS HAD BEEN SHOT THROUGH THE SIDEWALL AND TRIED TO FIX BY RIVERSIDE. THAT WOULD NOT BE ACCEPTED BY ANYONE PURCHASING THIS UNIT. I EXPECT TO GET PAID FOR THE WORK THAT IS COMPLETED OR I WILL HAVE TO GET MY SALES MANAGER INVOLVED.

BEN HOFFMAN

SERVICE EXPERT

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. [BHOFFMAN@AMERICANRVCENTER.COM](mailto:BHOFFMAN@AMERICANRVCENTER.COM)

---

**From:** Warranty @Riverside RV <[warranty@goriversiderv.com](mailto:warranty@goriversiderv.com)>  
**Sent:** Tuesday, June 22, 2021 2:43 PM  
**To:** Ben Hoffman <[bhoffman@americanrvcenter.com](mailto:bhoffman@americanrvcenter.com)>  
**Cc:** BJ Wright <[bjwright@americanrvcenter.com](mailto:bjwright@americanrvcenter.com)>  
**Subject:** RE: 10669 - 2021 RIVERSIDE RV INTREPID 281DDB Ser#: 59CCC3827ML003976,

If you wanted the trailer to come back to the factory why did you do work on it?



Thanks and have a good day,  
*Connie Wilfong*  
Warranty Manager  
Riverside RV

1775 E US 20  
Lagrange, IN 46761  
260-499-4578  
Ext. 110

**From:** Ben Hoffman <[bhoffman@americanrvcenter.com](mailto:bhoffman@americanrvcenter.com)>  
**Sent:** Monday, June 21, 2021 4:34 PM  
**To:** Warranty @Riverside RV <[warranty@goriversiderv.com](mailto:warranty@goriversiderv.com)>  
**Cc:** BJ Wright <[bjwright@americanrvcenter.com](mailto:bjwright@americanrvcenter.com)>  
**Subject:** Re: 10669 - 2021 RIVERSIDE RV INTREPID 281DDB Ser#: 59CCC3827ML003976,

WE HAVE PARTS THAT ARE SITTING ON THE SHELF FOR THIS UNIT AND WE HAVE ALSO FIXED THINGS ON THIS UNIT BEFORE YOU TOOK IT

BEN HOFFMAN

SERVICE EXPERT

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. [BHOFFMAN@AMERICANRVCENTER.COM](mailto:BHOFFMAN@AMERICANRVCENTER.COM)

---

**From:** Warranty @Riverside RV <[warranty@goriversiderv.com](mailto:warranty@goriversiderv.com)>  
**Sent:** Monday, June 21, 2021 12:30 PM  
**To:** Ben Hoffman <[bhoffman@americanrvcenter.com](mailto:bhoffman@americanrvcenter.com)>  
**Cc:** BJ Wright <[bjwright@americanrvcenter.com](mailto:bjwright@americanrvcenter.com)>  
**Subject:** RE: 10669 - 2021 RIVERSIDE RV INTREPID 281DDB Ser#: 59CCC3827ML003976,

We will repair all of this when we get it back.



Thanks and have a good day,

*Connie Wilfong*

Warranty Manager

Riverside RV

1775 E US 20

Lagrange, IN 46761

260-499-4578

Ext. 110

**From:** Ben Hoffman <[bhoffman@americanrvcenter.com](mailto:bhoffman@americanrvcenter.com)>

**Sent:** Tuesday, June 15, 2021 1:45 PM

**To:** Warranty @Riverside RV <[warranty@goriversiderv.com](mailto:warranty@goriversiderv.com)>

**Cc:** BJ Wright <[bjwright@americanrvcenter.com](mailto:bjwright@americanrvcenter.com)>

**Subject:** 10669 - 2021 RIVERSIDE RV INTREPID 281DDB Ser#: 59CCC3827ML003976,

1. THE EMERGENCY EXIT WINDOW ON THE OFF-DOOR SIDE OF THE FRONT BEDROOM FELL OUT.
  - a. FELL OUT GETTING DELIVERED TO US
    - i. INSTALL NEW WINDOW
      1. LABOR 3.00
2. THE WHITE PLASTIC REFRIGERATOR ROOFTOP VENT FELL OFF.
  - a. vent cover on the roof came off, mounting screws too shortly
    - i. removed sealer from holes on vent lid removed screws found longer screws installed lid, installed longer screws. Sealed screw holes on the lid. touched up roof on end of the vent
      1. LABOR 1.0
3. THE MAIN DOOR IS VERY HARD TO OPEN (REAR DOOR) FROM INSIDE AND OUTSIDE
  - a. main entry door hitting striker plate hard to close
    - i. removed screws in striker plate installed longer screws to pull striker plate in deeper so it does not hit .keep adjusting till door closes properly
      1. LABOR 0.6
4. OUTSIDE FRIDGE IN OUTSIDE KITCHEN IS LOOSE AND NOT FASTENED DOWN
  - a. THE FRIDGE IS NOT MOUNTED
    - i. MOUNT FRIDGE TO THE BOTTOM
      1. LABOR 0.3
5. OUTSIDE KITCHEN SLIDE THAT HOLDS THE GRILL WILL NOT OPEN ALL THE WAY
  - a. OUTSIDE KITCHEN PULLOUT FOR GRIDDLE WILL NOT PULL OUT ALL THE WAY
    - i. REMOVED GRIDDLE AND REMOVED SLIDING DRAWER (HAD TO REMOVE SCREW FROM GUIDE RAIL TO GET DRAWER OUT. FOUND THE OTHER 2 SCREWS HAD PULLED OUT KEEPING THE DRAWER GLIDE FROM PULLING OUT. REMOVED SCREWS GOT LONGER SCREWS AND INSTALLED INTO DRAWER GLIDE ADDED 2 EXTRA SCREWS ON BOTH SIDES. REASSEMBLED DRAWER TESTED OPERATION IT NOW PULLS OUT ALL THE WAY. INSTALLED GRIDDLE ON DRAWER
      1. LABOR 0.5
6. BATHROOM DOOR HARD TO OPEN AND CLOSE
  - a. door hitting Striker plate
    - i. removed striker plate reinstalled drilled new screw holes, had to countersink screw holes in striker plate deeper to keep screws from rubbing door
      1. LABOR 0.4
7. THE BEDROOM SLIDING DOOR IS LOOSE AND STUCK IN THE DOORWAY

- a. BEDROOM DOOR DRAGGING FLOOR
  - i. REMOVED COVER AT TOP OF DOOR TO ACCESS DOOR ROLLERS, PUT ROLLER IN MOUNT ON TOP OF DOOR, ADJUSTED DOOR ROLLERS, AND INSTALLED DOOR GUIDE AT BOTTOM OF DOOR. INSTALLED PANEL ABOVE DOOR
    1. LABOR 0.5
8. A/C DIVIDER IS MISSING
  - a. YOU HAVE THE TRAILER
  - b. YOU NEED TO FIX THIS
9. THE AC DUCTWORK NOT TAPPED AND SHOOTING AIR IN THE ATTIC BOARD IS BROKEN ABOVE THE DUCT
  - a. MAKE NEW BOARD AND INSTALLED IT AND TAPED
    - i. TESTED AND WORKS OK
      1. LABOR 1.0
10. AC BOLTS MISSING
  - a. 2 BOLTS MISSING ON THE A/C
    - i. FOUND MISSING BOLTS IN PACKAGE WITH ALL THE PAPERWORK FROM MANUFACTURE. REMOVED COVER ON CEILING REMOVED FILTERS AND FOUR MOUNTING SCREWS. INSTALLED THE TWO MISSING AC MOUNTING BOLTS, INSTALLED COVER FILTERS AND SCREWS
      1. LABOR 0.4
11. BRAKE AWAY SWITCH HANGING AND BUSTED
  - a. brake away switch busted and hanging off
    - i. removed mounting screw, cut wires installed new switch, mounting screw. wired in a new switch, tested operation
      1. LABOR 0.5
12. DRAWER NEXT TO BATHROOM DRAWER GLIDE MISSING BEARINGS
  - a. THE BEARINGS ARE MISSING
  - b. NEED TO INSTALL THE DRAWER GLIDES
    - i. WE HAVE THE DRAW GLIDES HERE SO WE NEED TO INSTALL
      1. LABOR 0.8
13. DRAWERS NET TO THE BATHROOM THE ARMS ARE FALLING OFF
  - a. YOU NEED TO FIX THIS
    - i. YOU HAVE THE UNIT
14. BLIND ON BOTTOM BUNK WILL NOT STAY UP
  - a. blind will not stay up
    - i. removed screw-in string tensioner for blind tightened up the string in eyelet installed eye and installed screw tested blind it stays up now
      1. LABOR 0.3
15. THE GALLEY TANK LEVEL INDICATOR DOES NOT REGISTER A READING.
  - a. GALLEY TANK LEVEL INDICATOR DOES NOT READ
    - i. TESTED CUT UNDER BELLY TO GET ACCESS TO TANK AND WIRING. CHASED WIRES CHECKED CONNECTIONS, TESTED DIODE PACK DOES NOT WORK HOOKED A TEST DIODE PACK IN A GLASS OF WATER, AND MONITOR PANEL WORKS. INSTALLED A NEW DIODE PACK STILL NOT WORKING CHANGED GROUND WIRE FROM TANK TO WIRING HARNESS IT NOW WORKS BUT UNDERBELLY BACK UP AND TAPED SAME INSTALLED SCREWS TO HOLD UNDERBELLY UP
      1. LABOR 2.0
16. WATER LEAK BEHIND WATER HEATER
  - a. THE WATERLINE BEHIND THE WATER HEATER HAS A CUT IN IT

- i. WATERLINE BEHIND WATER HEATER IS SPRAYING WATER, FOUND CUT IN LINE NEAR ELBOW REMOVED CLAMP PULLED WATER LINE OFF FOUND CUT, TRIMMED WATER LINE OFF, INSTALLED NEW CLAMP AND INSERTED ELBOW TIGHTENED CLAMP. PRESSUREIZED SYSTEM CHECKED FOR LEAKS NO LEAK
1. LABOR 0.5

PICS ARE ON THE WAY

BEN HOFFMAN

SERVICE EXPERT

AMERICAN RV CENTER

600 EAST BASELINE RD

EVANSVILLE, IN 47725

PH. 812-867-5200 EXT 263

FAX. 812-868-1012

EMAIL. [BHOFFMAN@AMERICANRVCENTER.COM](mailto:BHOFFMAN@AMERICANRVCENTER.COM)