

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 12286B

Date In: 07 JUL 25 Author: KOTT
Promised Date: 18 JUL 25 Stock No: 11394
: Year: 2025
Customer Name: 16686 - VREDEVELD, JAS Manufacturer: FOREST RIVER
Address: 630 COVENTRY DRIVE Brand: CEDAR CREEK EXPERIENCE
: PLOVER, WI Model: 39RKB
Postal/Zip: 54467 Miles/Hrs: 0
Phone#(res): 715-496-1976 Exterior Color:
Phone#(bus): Unit Type: FW-FIFTH WHEEL
Cell Phone: License#:
Email: JASON.VREDEVELD@AIG.CO Tag#: DEL@ST-7/18@9
Purchased Date: 28 APR 25 :
Delivery Date: 18 JUL 25 :
InService Date: :
Serial#: 4X4FCRR23TS235053 :

Job # Description JOB INFORMATION Type Bill To

WARR COMPLAINT: WARRANTY REPAIR 1 - The side of the W 1021 FORES
refer is dented
CAUSE: Arrived this way from mfg PLEASE ORDER
NEW SET OF TOP DOORS FOR THE SAMSUNG
REFER. PICS TAKEN OF TAG ON INTERIOR
M#RF18A5101SR/AA
CORRECTION: REQUEST 1 HOUR OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 2 - The awning lights on W 1021 FORES
door side slide 2nd awning there is a
area where lights do not light up
CAUSE: Came from mfg this way PLEASE ORDER A
NEW SET OF AWNING LIGHTS INNER ARM TO
INNER ARM OF AWNING MEASURES 126"
CORRECTION: REQUEST 1 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 3 - bottom of panels W 1021 FORES
have rough cuts in various places
throughout unit
CAUSE: Mfg
CORRECTION: I cut away the shards of wood on end of
panel beneath the desk and cut away
excess paper from wall next to desk used
a nail punch and pounded in 5 staples
then filled with putty looks as it
should now REQUEST .30 HOURS OF LABOR
WARR COMPLAINT: WARRANTY REPAIR 4 -overhead cabinetry W 1021 FORES
the cabinet doors both sides of the
stove the doors are crooked they need
adjusting

Continued on page 2

Work Order : 12286B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
        CAUSE:             Mfg product
        CORRECTION:        Adjusted as much as possible they do
                                close REQUEST .30 HOURS OF LABOR
WARR    COMPLAINT:        WARRANTY REPAIR 5 - on the slide out           W    1021    FORES
                                next to the desk there is a loose piece
                                of trim
        CAUSE:             Loose trim
        CORRECTION:        Used pin nailer to secure trim REQUEST
                                .20 HOURS OF LABOR
WARR    COMPLAINT:        WARRANTY REPAIR 6 - there is a loose           W    1021    FORES
                                panel in the hallway
        CAUSE:             Wall panel uneven after nailing
        CORRECTION:        I cut a wide batten trim to 53 3/4" and
                                nailed over the wall panel seem to cover
                                the unevenness of the wall REQUEST .50
                                HOURS OF LABOR
WARR    COMPLAINT:        WARRANTY REPAIR 7 - to the left of the           W    1021    FORES
                                wardrobe there is a loose piece of trim
        CAUSE:             Loose trim near bottom
        CORRECTION:        Used pin nailer to secure REQUEST .20
                                HOURS OF LABOR
WARR    COMPLAINT:        WARRANTY REPAIR 8 - the overhead           W    1021    FORES
                                cabinets in the kitchen above the stove
                                the corners are peeling up
        CAUSE:             Gaps and peeling finish
        CORRECTION:        I used putty to fill the gaps and I
                                rubbed off the peeled finish REQUEST .20
                                HOURS OF LABOR
WARR    COMPLAINT:        WARRANTY REPAIR 9 -the sofas bottom rear W    1021    FORES
                                fabric is ripped and you can see that
                                the wood frame has a crack in it
        CAUSE:             The back of sofa fabric is ripped and
                                the wood frame is cracked PLEASE ORDER
                                A NEW SOFA PICS TAKEN OF TAGS AND SOFA
                                AND RIP AND CRACK
        CORRECTION:        ..... REQUEST 1.5 HOURS OF LABOR
WARR    COMPLAINT:        WARRANTY REPAIR 10 - 2 holes in the           W    1021    FORES
                                dicor
        CAUSE:             Bubbles in sealant on roof
        CORRECTION:        Cleaned areas then resealed REQUEST .50
                                HOURS OF LABOR

```

```

*****
Job # Part No Description           PARTS           Bill to Qty Price Total
*****
WARR0 82202790 SOFA, 72" TRIFOLD, ETERNAL T W-1021           0 1,054.94 0.00

```

Continued on page 3

Work Order : 12286B

```
*****
Job#  Lab Code  Description  LABOUR  Mech Bill to    Hrs    Rate    Total
*****
ARR01 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR02 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR03 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR04 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR05 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.36   140.00   50.40
ARR06 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.14   140.00   19.60
ARR07 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR08 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR09 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
ARR10 Z992      MISC LABOUR CODE (WARR HOD W-1021    0.50   140.00   70.00
*****
```

```
*****
Job #  Excode    Description  EXTRAS      bill to    Qty    Price    Total
*****
ARR01  SSE        SHOP SUPPLIES - EXTERNAL  W-1021    1.00    0.00    0.00
*****
```

```
*****
                                BILLINGS SUMMARY
Type Bill Id      Parts    Labour    Sublet    Extras    Tax    Total
*****
W      1021          0.00    700.00    0.00    0.00    0.00    700.00
      Totals          0.00    700.00    0.00    0.00    0.00    700.00
*****
```

&k2S
&k0S