

GREENEWAY, INC.
 8220 STATE HWY 13 SOUTH
 WISCONSIN RAPIDS WI
 US
 54494
 (715) 325-5170

WORK ORDER # 10097B

Date In:	05 MAR 24	Author:	MGRAY
Promised Date:	31 DEC 24	Stock No:	11103
:	:	Year:	2024
Customer Name:	1000 - GREENEWAY RV SA	Manufacturer:	FOREST RIVER
Address:	8220 STATE HWY 13 SOUT	Brand:	PUMA DESTINATION
:	WISCONSIN RAPIDS, WI	Model:	39PQB
Postal/Zip:	54494	Miles/Hrs:	0
Phone#(res):	800-758-2272	Exterior Color:	
Phone#(bus):		Unit Type:	TT-TRAVEL TRAILER
Cell Phone:		License#:	
Email:	NONE	Tag#:	
Purchased Date:		:	:
Delivery Date:		:	:
InService Date:		:	:
Serial#:	4X4TPUR29RP101430	:	:

Job #	Description	JOB INFORMATION	Type	Bill To
DAF	COMPLAINT:	DAF-WARRANTY REPAIRS- 1. STAPLE MARKS ON MAIN SLIDE TOP CORNER REAR	W	1021 FORES
	CAUSE:	Staple marks per complaint WILL NEED .40 FOR REPAIRS.		
	CORRECTION:	Apply puddy to staple holes. Looks OK.		
WARR	COMPLAINT:	WARRANTY REPAIR 1 - Range Hood not getting power light and fan will not turn on.	W	1021 FORES
	CAUSE:	Range hood not functioning. WILL NEED A NEW FUSE AND .40 FOR REPAIRS		
	CORRECTION:	During prep, noticed fuse was missing for furnace, which corrected the range hood issue of not getting power.		
WARR	COMPLAINT:	WARRANTY REPAIR 2 - Sewer Cap Missing needs new one, likely fell off in transport	W	1021 FORES
	CAUSE:	One Missing sewer cap, and one damaged. Unit has 3 dumps and 6 tanks. WILL NEED .50 FOR REPAIRS AND TWO NEW SEWER CAPS.		
	CORRECTION:	Replaced two sewer caps. Good to go.		
WARR	COMPLAINT:	WARRANTY REPAIR 3 - Door Knob on BH bathroom door broken off a d laying in pieces in bunkbed. Damaged, needs to be ordered.	W	1021 FORES
	CAUSE:	Door knot broken in pieces, cant be fixed without a new part. WILL NEED .70 FOR REPAIRS		
	CORRECTION:	Order new doorknob via warranty.		

Continued on page 2

Work Order : 10097B

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
                INSTALLED NEW DOOR KNOB
WARR    COMPLAINT:  WARRANTY REPAIR 4 - Awning tracking           W    1021    FORES
                incorrectly after initial test.
        CAUSE:      Awning fabric needs adjustment, tracking
                toward rear of unit when retracted. WILL
                NEED .50 FOR REPAIRS.
        CORRECTION: Adjusted fabric slightly toward front of
                unit, no longer tracking badly. Tested
                OK.
    
```

```

*****
Job # Part No   Description           PARTS           Bill to   Qty   Price   Total
*****
WARR0 F100207689 KNOB, PASSAGE DOOR, MATTE W-1021       1       7.27     7.27
    
```

```

*****
Job# Lab Code Description           LABOUR           Mech Bill to   Hrs   Rate   Total
*****
  DAF Z991    DAF-WARRANTY REPAIR           RW    W-1021       0.10  115.00  11.50
ARR01 Z992    MISC LABOUR CODE (WARR RW    W-1021       0.50  115.00  57.50
ARR02 Z992    MISC LABOUR CODE (WARR RW    W-1021       0.50  115.00  57.50
ARR03 Z992    MISC LABOUR CODE (WARR JT    W-1021       0.50  115.00  57.50
ARR03 Z992    MISC LABOUR CODE (WARR RW    W-1021       0.00  115.00   0.00
ARR04 Z992    MISC LABOUR CODE (WARR RW    W-1021       0.50  115.00  57.50
    
```

```

*****
Job # Excode Description           EXTRAS           bill to   Qty   Price   Total
*****
ARR01 SSE      SHOP SUPPLIES - EXTERNAL      W-1021       1.00   0.00   0.00
ARR03 FRT      FREIGHT                        W-1021       1.00  19.46  19.46
    
```

```

*****
                BILLINGS SUMMARY
Type Bill Id           Parts   Labour   Sublet   Extras   Tax   Total
*****
W    1021                7.27   241.50   0.00    19.46   0.00  268.23
                Totals                7.27   241.50   0.00    19.46   0.00  268.23
    
```

&k2S
&k0S