

#1108

Sent 2/12/24

DAF: Dealer Unit Inspection Form



Forest River, Inc.
2551 Century Drive
Goshen, IN 46528
USA

Short VIN/Unit: PUP101869
Model/Item: PUT402LFT
Dealer: GREENEWAY INC

1. Forest River allows for a secondary inspection, which must take place within **3 business days** from the **delivery date** for warranty consideration.
2. Dealer Unit Inspection Form is to document substantial damage and shortages, not to note minor defects in material or workmanship.
3. If the Dealer is unable to perform this inspection within **3 business days**, the appropriate Warranty Department must be notified via email or phone.
4. The form must be signed and attached to the VIN on Dealer Connect **within 24 hours after the secondary inspection**.
5. Warranty claims must be submitted and resolved no later than **6 months from delivery** for coverage and payment.

Circle Yes or No if item was received, and if applicable:

Keys	<input checked="" type="radio"/> Yes	<input type="radio"/> No
BBQ Grill	<input type="radio"/> Yes	<input type="radio"/> No
Power Cord	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Warranty Packet	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Sink cover	<input checked="" type="radio"/> Yes	<input type="radio"/> No
Jack Handles	<input checked="" type="radio"/> Yes	<input type="radio"/> No
TV 1	<input checked="" type="radio"/> Yes	<input type="radio"/> No
TV 2	<input type="radio"/> Yes	<input type="radio"/> No
Remotes	<input checked="" type="radio"/> Yes	<input type="radio"/> No

List Any Miscellaneous Comments Regarding Condition of Unit:

- Seam Tape all around
- Ceiling trim top right corner ODS Front.
- Gap under trim under overhang on left.
- Discolored puddy marks
- Gap in window trim DS side Row
- Staple marks in ODS wall at top of stairs

List Any Additional Missing Items:

Suggested areas to inspect:	
Unit Cleanliness	If no, explain:
Condition of Flooring	
Cabinetry Damage	If yes, explain:
Appliance Condition	microwave in worky
Furniture Tears/Stains	If yes, explain:
Frame/Chassis Condition	
Roof Components	
Roof Material	
Awning Fabric	
ODS/DS Walls & Graphics	
Unit Front & Graphics	
Unit Rear & Graphics	
Additional Notations	

- Bracket on lg closet door in Bedroom on bottom bolt
- Front window shades have a bunch of loose ends
- Hollowing ~~on~~ window shade has hole in it
- Mark on front corner of Desk in Bedroom

Unit/Underside has been washed by the Dealership Yes No Date Washed _____

Dealer Signature _____

Date 2/18/24