

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 10595

Date In: 04 JUN 24 Author: TPASSER  
Promised Date: 04 JUL 24 Stock No: 11087  
: Year: 2022  
Customer Name: 17339 - WOHLHOEFER, DA Manufacturer: FOREST RIVER  
Address: 9609 IDELL AVE Brand: PUMA TT  
: SPARTA, WI Model: 31FKRK  
Postal/Zip: 54656 Miles/Hrs: 0  
Phone#(res): 608-487-5646 Exterior Color:  
Phone#(bus): Unit Type: TT-TRAVEL TRAILER  
Cell Phone: License#:  
Email: kimbertimmie@hotmail.c Tag#:  
Purchased Date: 21 MAY 24 :  
Delivery Date: 31 MAY 24 :  
InService Date: :  
Serial#: 4X4TPUG26NP097205 :

\*\*\*\*\*

Job #	Description	JOB INFORMATION	Type	Bill To
SC	SERVICE CALL TO SHW SITE 87		I	FSC FREE
WARR	COMPLAINT: CMR CALLED STATING THAT ISSUES FOUND AFTER UNIT DELIVERED 5/31 - WALLPAPER PEELING BY LEFT CORNER OF FRONT WINDOW OVER HITCH.		W	1021 FORES
	CAUSE: in front of unit by kitchen counter top on left side is a little bubbled but no water damage it cause from glue letting loose possible seam tape NEED .3 FOR REPAIR			
	CORRECTION: possible seam tape to repair....			
WARR	COMPLAINT: SHOWER BASIN HAS A CRACK BETWEEN 2 SCREWS		W	1021 FORES
	CAUSE: pics and measurements taken theres a crack on outside lower base of shower pan pics and measurements taken would have to completely remove shower to change pan NEED 4 HRS TO REMOVE AND REPAIR.			
	CORRECTION: shower pan ....			
WARR	COMPLAINT: CMR REPORTS AFTER UNIT PERMANENTLY PARKED ENTRY DOORS WILL NOT CLOSE WITHOUT SLAMMING. CMR REMOVED STRIKE PLATE FROM REAR DOOR TO GET IT TO CLOSE - IT IS IN UNIT IN DRAWER BY DOOR OR CMR MAY LEAVE ON COUNTER.		W	1021 FORES
	CAUSE: pics taken of entry doors and tags I found striker plates for both doors out			

Continued on page 2

Work Order : 10595

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      of adjustments and need longer screws to
      secure to framework
CORRECTION: adjustments made to both striker plates
and longer screws was used I also tested
the doors after repairs
WARR   COMPLAINT:  CMR REPORTING HE THINKS THERE SHOULD BE W   1021   FORES
      A LENS COVER OVER THE LIGHT IN THE
      PANTRY BUT IT IS MISSING.
CAUSE:   pics and measurements taken the pantry
ceiling light is missing a cover with
button in middle NEED .20 FOR REMOVAL
AND REPAIR
CORRECTION: Will need a light cover with button in
middle...
WARR   COMPLAINT:  CMR REPORTING THE VENT IN THE BATHROOM W   1021   FORES
      WILL NOT OPEN - JT FOUND DURING SHOW
      THRU AND TOLD CMR IT WOULD BE ADDRESSED
      BEFORE DELIVERY, BUT IT STILL DOES NOT
      OPEN.
CAUSE:   what I found was the ceiling vent lid
was stuck to rubber gasket and the cover
wouldn't open
CORRECTION: opened the ceiling vent lids and sprayed
silicone Spray on gasket and tighten the
manual handle has well the the lid opens
  
```

```

*****
Job#  Lab Code  Description  LABOUR  Mech Bill to  Hrs  Rate  Total
*****
  SC SC      SERVICE CHARGE      JS  I-FSC      0.00  70.00  0.00
WARR1 Z992    CRACKED SHOWER PAN  JS  W-1021     0.50  115.00  57.50
WARR2 RV30C-6  ENTRY DOOR ADJUST  JS  W-1021     0.30  115.00  34.50
WARR3 Z992    PANTRY LIGHT LENS   JS  W-1021     0.20  115.00  23.00
WARR4 RV25-13 VENT DIAGNOSE RVDA VEN JS  W-1021     0.30  115.00  34.50
WARR WARR    MANUFACTURER WARRANTY JS  W-1021     0.50  115.00  57.50
  
```

```

*****
Job #  Excode  Description  EXTRAS  bill to  Qty  Price  Total
*****
  SC SC      SERVICE CALL      I-FSC  1.00  3.75  3.75
  SC SSE     SHOP SUPPLIES - EXTERNAL I-FSC  1.00  0.00  0.00
  
```

```

*****
                        BILLINGS SUMMARY
Type Bill Id  Parts  Labour  Sublet  Extras  Tax  Total
*****
I   FSC      0.00   0.00   0.00   3.75   0.00   3.75
W   1021     0.00  207.00  0.00   0.00   0.00  207.00
  
```

Continued on page 3

Work Order : 10595

\*\*\*\*\*

BILLINGS SUMMARY

Type Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
Totals	0.00	207.00	0.00	3.75	0.00	210.75

&k2S  
&k0S