

GREENEWAY, INC.
8220 STATE HWY 13 SOUTH
WISCONSIN RAPIDS WI
US
54494
(715) 325-5170

WORK ORDER # 10595

Date In: 04 JUN 24 Author: MZYWICKI
Promised Date: 18 SEP 24 Stock No: 11087
: Year: 2022
Customer Name: 17339 - WOHLHOEFER, DA Manufacturer: FOREST RIVER
Address: 9609 IDELL AVE Brand: PUMA TT
: SPARTA, WI Model: 31FKRK
Postal/Zip: 54656 Miles/Hrs: 0
Phone#(res): 608-487-5646 Exterior Color:
Phone#(bus): Unit Type: TT-TRAVEL TRAILER
Cell Phone: License#:
Email: kimbertimmie@hotmail.c Tag#: 9/18 - WARR APPROVED
Purchased Date: 21 MAY 24 :
Delivery Date: 31 MAY 24 :
InService Date: :
Serial#: 4X4TPUG26NP097205 :

Job # Description JOB INFORMATION Type Bill To

SC SERVICE CALL TO SHW SITE 87 I FSC FREE
WARR COMPLAINT: CMR CALLED STATING THAT ISSUES FOUND W 1021 FORES
AFTER UNIT DELIVERED 5/31 - WALLPAPER
PEELING BY LEFT CORNER OF FRONT WINDOW
OVER HITCH.
CAUSE: in front of unit by kitchen counter top
on left side is a little bubbled but no
water damage it cause from glue letting
loose possible seam tape Front window
has wrinkles in the wall paper neat the
ring for window left side.
CORRECTION: possible seam tape to repair.... Removed
ring and glued and reset ring.
WARR COMPLAINT: SHOWER BASIN HAS A CRACK BETWEEN 2 W 1021 FORES
SCREWS
CAUSE: pics and measurements taken theres a
crack on outside lower base of shower
pan pics and measurements taken would
have to completely remove shower to
change pan NEED 4 HRS TO REMOVE AND
REPAIR.
CORRECTION: shower pan
WARR COMPLAINT: CMR REPORTS AFTER UNIT PERMANENTLY W 1021 FORES
PARKED ENTRY DOORS WILL NOT CLOSE
WITHOUT SLAMMING. CMR REMOVED STRIKE
PLATE FROM REAR DOOR TO GET IT TO CLOSE
- IT IS IN UNIT IN DRAWER BY DOOR OR CMR
MAY LEAVE ON COUNTER.

Continued on page 2

Work Order : 10595

```

*****
Job #   Description           JOB INFORMATION           Type Bill To
*****
      CAUSE:      pics taken of entry doors and tags  I
                  found striker plates for both doors out
                  of adjustments and need longer screws to
                  secure to framework
      CORRECTION: adjustments made to both striker plates
                  and longer screws was used I also tested
                  the doors after repairs
WARR    COMPLAINT: CMR REPORTING HE THINKS THERE SHOULD BE  W    1021    FORES
                  A LENS COVER OVER THE LIGHT IN THE
                  PANTRY BUT IT IS MISSING.
      CAUSE:      pics and measurements taken the pantry
                  ceiling light is missing a cover with
                  button in middle NEED .20 FOR REMOVAL
                  AND REPAIR
      CORRECTION: Will need a light cover with button in
                  middle....
WARR    COMPLAINT: CMR REPORTING THE VENT IN THE BATHROOM  W    1021    FORES
                  WILL NOT OPEN - JT FOUND DURING SHOW
                  THRU AND TOLD CMR IT WOULD BE ADDRESSED
                  BEFORE DELIVERY, BUT IT STILL DOES NOT
                  OPEN.
      CAUSE:      what I found was the ceiling vent lid
                  was stuck to rubber gasket and the cover
                  wouldn't open
      CORRECTION: opened the ceiling vent lids and sprayed
                  silicone Spray on gasket and tighten the
                  manual handle has well the the lid opens

```

```

*****
Job # Part No   Description      PARTS      Bill to   Qty    Price    Total
*****
WARR1 82205867  SHOWER PAN, 34" RADIUS W/9. W-1021      1    156.93    156.93
WARR3 822015389 LIGHT,LED INTERIOR, 4-1/2" W-1021      1     2.12     2.12
WARR  822032415 SEAM TAPE, 1", MELIA PLATIN W-1021     30     0.13     3.90

```

```

*****
Job#  Lab Code  Description      LABOUR    Mech Bill to      Hrs    Rate    Total
*****
   SC SC      SERVICE CHARGE      JS    I-FSC      0.00    70.00     0.00
WARR1 Z992    CRACKED SHOWER PAN      JS    W-1021     0.10   115.00    11.50
WARR2 RV30C-6 ENTRY DOOR ADJUST      JS    W-1021     0.20   115.00    23.00
WARR3 Z992    PANTRY LIGHT LENS      JS    W-1021     0.05   115.00     5.75
WARR4 RV25-13 VENT DIAGNOSE RVDA VEN JS    W-1021     0.20   115.00    23.00
WARR WARR    MANUFACTURER WARRANTY JS    W-1021     0.00   115.00     0.00
WARR WARR    MANUFACTURER WARRANTY TD    W-1021     0.01   115.00     1.15
WARR1 WARR    MANUFACTURER WARRANTY JS    W-1021     1.90   115.00   218.50
WARR3 WARR    MANUFACTURER WARRANTY TD    W-1021     0.15   115.00    17.25
WARR WARR    MANUFACTURER WARRANTY TD    W-1021     0.29   115.00    33.35

```

Continued on page 3

Work Order : 10595

```

*****
Job #  Excode   Description   EXTRAS      bill to      Qty      Price      Total
*****
   SC   SC      SERVICE CALL      I-FSC      0.00      3.75      0.00
   SC   SSE      SHOP SUPPLIES - EXTERNAL  I-FSC      1.00      0.00      0.00
WARR3   FRT      FREIGHT              W-1021      1.00     21.00     21.00
WARR1   FRT      FREIGHT & CRATE FOR SHOWER W-1021      1.00    199.39    199.39
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id      Parts      Labour      Sublet      Extras      Tax      Total
*****
W      1021      162.95      333.50      0.00      220.39      0.00      716.84

      Totals      162.95      333.50      0.00      220.39      0.00      716.84
*****

```

&k2S
&k0S